

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION



1. LICENSEE Orion Genomics, LLC REPORT NUMBER(S) 2006-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-35319	4. LICENSE NUMBER(S) 24-32213-01	5. DATE(S) OF INSPECTION 3/27/2006	
6. INSPECTION PROCEDURES USED 87126		7. INSPECTION FOCUS AREAS 03.01-03.07	

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03620	2. PRIORITY K5	3. LICENSEE CONTACT Tracy Rohling, Tech Ops Manager	4. TELEPHONE NUMBER 314-615-6984
------------------------------------	--------------------------	---	--

Main Office Inspection Next Inspection Date: 3/2007 (no licensed material)

Field _____

Temporary Job Site _____

PROGRAM SCOPE

The licensee is authorized to use P-32 for research and development as defined in 10 CFR 30.4. However, the license has not possessed material since the license was issued in April 2000.

Performance Observations

The inspector verified through interviews, document review, independent observations and radiation surveys that the licensee had not possessed licensed material since the license was issued. According to the licensee, the Radiation Safety Officer has not been employed at the facility since May 2002. The licensee is being cited in a Notice of Violation (NOV) with response required for failure to have a Radiation Safety Officer as it may compromise the program if the licensee possesses licensed material in the future. Pursuant to MC 2800 (Section 05.03(a)(5), the licensee is scheduled to be inspected 12 months for the month of the inspection.