

HALLIBURTON

1015 W. BOIS D'ARC • POST OFFICE DRAWER 1431 • DUNCAN, OK 73536-0103

PHONE 580.251.3949 • FAX 580.251.4050

RECEIVED

JUN 08 2006

DNMS

June 2, 2006

U. S. Nuclear Regulatory Commission
Office of the Administrator
Region IV
611 Ryan Plaza Drive, Suite 400
Arlington, TX 76011-4005

Subject: Follow up Written Report of Lost Devices

Dear Mr. Mallett:

Halliburton wishes to report the recovery of two generally licensed devices which were located on the Rowan Odessa drilling rig that sank as a result of hurricane Rita. Both devices that were on board were recovered and are listed below:

Halliburton 10SD Device Serial Number V32-0246 containing Isotope Products Laboratories sealed source model A3906 with 11.9 mCi of Cs-137, serial number DB-076.

Halliburton 10SD Device Serial Number W2C-097 containing Isotope Products Laboratories sealed source model A3906 with 10 mCi of Cs-137, serial number DB-140.

If you need additional information, please advise.

Sincerely,



Steve Woods

Sr. Radiation Safety Officer