

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1 LICENSEE/LOCATION INSPECTED: Alpena Reg Med Ctr 1501 Chisholm St Alpena, MI 49707 REPORT 2006-001	2 NRC/REGIONAL OFFICE US NRC Region III 2443 Warrsville Rd Suite 210 Lisle, IL 60532
---	--

3 DOCKET NUMBER(S) 03013274	4. LICENSEE NUMBER(S) 21-17754-01	5. DATE(S) OF INSPECTION June 15, 2006
--------------------------------	--------------------------------------	---

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

2. Previous violation(s) closed.

3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	G. Parker		6/15/06

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION



1. LICENSEE Alpena Reg Med Ctr REPORT NUMBER(S) 2006-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-13274	4. LICENSE NUMBER(S) 21-17754-01	5. DATE(S) OF INSPECTION 6/15/06	
6. INSPECTION PROCEDURES USED 87133	7. INSPECTION FOCUS AREAS 03.01-03.07		
SUPPLEMENTAL INSPECTION INFORMATION			
1. PROGRAM CODE(S) 2120	2. PRIORITY 3	3. LICENSEE CONTACT Marty Andrzejewski	4. TELEPHONE NUMBER 989/356-7202
<input checked="" type="checkbox"/> Main Office Inspection		Next Inspection Date: 6/2009	
Field Office _____			
Temporary Job Site _____			

PROGRAM SCOPE

Licensee is the regional hospital located in Alpena, MI. Licensee has a medium sized nuclear medicine program conducting a complement of nuclear medicine procedures primarily cardiac studies. The licensee has two techs and one student tech who perform approximately 10 procedures per day. This hospital receives its radiopharmaceuticals in the form of unit doses from Cardinal Health and occasional non-standard doses from Mallinckrodt. This licensee also receives a small week old generator for weekend add ons because of the distance to the nearest nuclear pharmacy.

Performance Observations

The inspector toured the facilities and interviewed authorized users and staff members. Each appeared knowledgeable in radiation safety and isotope handling techniques. Licensee personnel demonstrated package receipt procedures for the inspector. Staff members also demonstrated proper rad waste handling practices. Independent surveys by the inspector did not detect any abnormal readings and were within the expected range.

The inspector observed members of the nuclear medicine staff perform injections of radiopharmaceuticals. Techniques employed by the staff demonstrated good handling practices as well as adequate knowledge of radiation safety. During the course of the inspection, no safety issues were identified.