
From: "Seeman, Glen A." <gaseema@nppd.com>
To: "David Loveless (E-mail)" <dpl@nrc.gov>
Date: 4/6/04 3:36PM
Subject: SW Valve Checklist and Top 100 Cutsets from Run without Recovery

David,

Attached are the two files we discussed this morning. They are:

- 1) The SW valve checklist procedure 2.2.71a. The valves are listed on page 18 - SW-1479, page 24 - SW-28 and page 28 - SW-1480.
- 2) An MSExcel file with the top 100 cutsets from the run without recovery of SW GW.

If you have problems with these files or have additional questions, please contact me.

Glen A Seeman
Risk Management Engineer
Equipment Reliability Department
NPPD - Cooper Nuclear Station
402-825-5174
email: gaseema@nppd.com

<<2.2.71A.wpd>> <<Top 100 Cutsets Dependency only.xls>>

CC: "Sutton, Kent E." <kesutto@nppd.com>