

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED:

**University Internal Medicine Specialists  
50 East Canfield Street  
Detroit, MI 48201**

2. NRC/REGIONAL OFFICE

**UNITED STATES  
NUCLEAR REGULATORY COMMISSION  
REGION III  
2443 WARRENVILLE ROAD, SUITE 210  
LISLE, IL 60532-4352**

REPORT 2006-001

3. DOCKET NUMBER(S)

**030-36522**

4. LICENSEE NUMBER(S)

**21-32499-01**

5. DATE(S) OF INSPECTION

**June 14, 2006**

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.


\_\_\_\_\_ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

**Licensee's Statement of Corrective Actions for Item 4, above.**

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	<b>Robert P. Hays</b>		<b>6/14/06</b>

*RPH*

*Docket File Information*  
**SAFETY INSPECTION REPORT  
AND COMPLIANCE INSPECTION**

1. LICENSEE <b>University Internal Medicine Specialists</b>		2. NRC/REGIONAL OFFICE <b>Region III</b>	
REPORT NUMBER(S) <b>2006-001</b>			
3. DOCKET NUMBER(S) <b>03036522</b>	4. LICENSE NUMBER(S) <b>21-32499-01</b>	5. DATE(S) OF INSPECTION <b>June 14, 2006</b>	
6. INSPECTION PROCEDURES USED <b>87130 (10/24/02)</b>	7. INSPECTION FOCUS AREAS <b>03.01- 03.07</b>		
<b>SUPPLEMENTAL INSPECTION INFORMATION</b>			
1. PROGRAM CODE(S) <b>02201</b>	2. PRIORITY <b>5</b>	3. LICENSEE CONTACT <b>Dorothy Austin, Off. Mgr.</b>	4. TELEPHONE NUMBER <b>313/745-4955</b>
<input checked="" type="checkbox"/> Main Office Inspection		Next Inspection Date: <b>June 2007</b>	
<input type="checkbox"/> Field Office			
<input type="checkbox"/> Temporary Job Site			

**PROGRAM SCOPE**

The licensee was a medical clinic authorized by the license to use any byproduct material permitted by 10 CFR 35.100, as needed for any uptake, dilution and excretion study permitted by 10 CFR 35.100, and 10 CFR 35.200, as needed (any except generators) for any imaging and localization study permitted by 10 CFR 35.200 at the location specified on the license. Licensed activities have not been initiated since the license has been issued, which was confirmed through interview of one nurse and the office manager. Since licensed activities have not yet been initiated, the next inspection should be scheduled at one year from the current inspection date.