



**Docket File Information**  
**SAFETY INSPECTION REPORT**  
**AND COMPLIANCE INSPECTION**



1. LICENSEE <b>Bristol-Myers Squibb Medical Imaging</b>		2. NRC/REGIONAL OFFICE <b>Region III</b> <b>2443 Warrenville Road</b> <b>Lisle, IL 60532</b>	
REPORT NUMBER(S) <b>2006-001</b>			
3. DOCKET NUMBER(S) <b>030-13288</b>	4. LICENSE NUMBER(S) <b>20-00320-19</b>	5. DATE(S) OF INSPECTION <b>July 13, 2006</b>	
6. INSPECTION PROCEDURES USED <b>87126</b>		7. INSPECTION FOCUS AREAS <b>03.01, 03.02, 03.03, 03.04, 03.05, 03.06, and 03.07</b>	
<b>SUPPLEMENTAL INSPECTION INFORMATION</b>			
1. PROGRAM <b>03214</b>	2. PRIORITY <b>E 5</b>	3. LICENSEE CONTACT <b>Donald Chartrand, RSO</b>	4. TELEPHONE NUMBER <b>978.671.8333</b>
<input type="checkbox"/> Main Office Inspection		Next Inspection Date: <u>July 2011</u>	
<input checked="" type="checkbox"/> Field Office <u>2684 Metro Blvd. Maryland Heights, MO</u>			
<input type="checkbox"/> Temporary Job Site			

**PROGRAM SCOPE**

This small distribution center of BMS (one of 4 in the U.S.) maintained a small inventory of radiopharmaceuticals (*Mo-99/Tc-99m* generators, *Xe-133*, *Sm-153* and *P-32*) at its Maryland Heights center. The facility maintained its inventory of materials to support customer needs in the Midwest. This facility did not process or manipulate RAM; the facility re-packaged RAM for distribution purposes only. An individual, working under contract through Associated Couriers, managed the day-to-day operations.

This inspection consisted of a tour of the lab and the radioactive material storage areas; review of selected records; interviews with licensee staff, and independent area surveys. The inspector observed licensee personnel perform inventories, package receipt surveys, opening packages and preparing packages for short-term storage within the storage areas. The inspector also observed the licensee's security of RAM and its use of personnel monitoring. The licensee informed the inspector that this facility expected to cease operations and would be closing in August 2006. The inspector discussed the licensee termination process with the site personnel and the corporate RSO.