

(10-2003)
10 CFR 2.201*Docket File Information*
**SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE Clinton Diagnostics, LLC REPORT NUMBER(S) 2006-001		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 03036580		4. LICENSE NUMBER(S) 21-32514-01	5. DATE(S) OF INSPECTION June 13, 2006
6. INSPECTION PROCEDURES USED 87130 (10/24/02)		7. INSPECTION FOCUS AREAS 03.01- 03.07	
SUPPLEMENTAL INSPECTION INFORMATION			
1. PROGRAM CODE(S) 02201	2. PRIORITY 5	3. LICENSEE CONTACT Sharon Galetti	4. TELEPHONE NUMBER 586/286-2350
<input checked="" type="checkbox"/> Main Office Inspection	Next Inspection Date: June 2007		
<input type="checkbox"/> Field Office			
<input type="checkbox"/> Temporary Job Site			

PROGRAM SCOPE

The licensee was a medical clinic authorized by the license to use any byproduct material permitted by 10 CFR 35.100, as needed for any uptake, dilution and excretion study permitted by 10 CFR 35.100, and 10 CFR 35.200, as needed (excluding greater than 30 microcuries of iodine-131) for any imaging and localization study permitted by 10 CFR 35.200 at the location specified on the license. Licensed activities have not been initiated since the license has been issued. Since licensed activities have not yet been initiated, the next inspection should be scheduled at one year from the current inspection date.