

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

| | | |
|--|--|---|
| 1. LICENSEE/LOCATION INSPECTED: Clinton Diagnostics, LLC 43475 Dalcama, Suite 110 Clinton Township, MI 48038 | 2. NRC/REGIONAL OFFICE <p style="text-align: center;"> UNITED STATES NUCLEAR REGULATORY COMMISSION REGION III 2443 WARRENVILLE ROAD, SUITE 210 LISLE, IL 60532-4352 </p> | |
| REPORT 2006-001 | 3. DOCKET NUMBER(S) <p style="text-align: center;">030-36580</p> | 4. LICENSEE NUMBER(S) <p style="text-align: center;">21-32514-01</p> |
| | | 5. DATE(S) OF INSPECTION <p style="text-align: center;">June 13, 2006</p> |

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.


_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

| Title | Printed Name | Signature | Date |
|---------------------------|-----------------------|--|----------------|
| LICENSEE'S REPRESENTATIVE | |  | |
| NRC INSPECTOR | Robert P. Hays | | 6/13/06 |

RPH

(10-2003)
10 CFR 2.201**Docket File Information**
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

| | | | |
|--|--|--|--|
| 1. LICENSEE Clinton Diagnostics, LLC REPORT NUMBER(S) 2006-001 | | 2. NRC/REGIONAL OFFICE Region III | |
| 3. DOCKET NUMBER(S) 03036580 | | 4. LICENSE NUMBER(S) 21-32514-01 | 5. DATE(S) OF INSPECTION June 13, 2006 |
| 6. INSPECTION PROCEDURES USED 87130 (10/24/02) | | 7. INSPECTION FOCUS AREAS 03.01- 03.07 | |
| SUPPLEMENTAL INSPECTION INFORMATION | | | |
| 1. PROGRAM CODE(S) 02201 | 2. PRIORITY 5 | 3. LICENSEE CONTACT Sharon Galetti | 4. TELEPHONE NUMBER 586/286-2350 |
| <input checked="" type="checkbox"/> Main Office Inspection | Next Inspection Date: June 2007 | | |
| <input type="checkbox"/> Field Office | | | |
| <input type="checkbox"/> Temporary Job Site | | | |

PROGRAM SCOPE

The licensee was a medical clinic authorized by the license to use any byproduct material permitted by 10 CFR 35.100, as needed for any uptake, dilution and excretion study permitted by 10 CFR 35.100, and 10 CFR 35.200, as needed (excluding greater than 30 microcuries of iodine-131) for any imaging and localization study permitted by 10 CFR 35.200 at the location specified on the license. Licensed activities have not been initiated since the license has been issued. Since licensed activities have not yet been initiated, the next inspection should be scheduled at one year from the current inspection date.