



TO: NRC Wash. CONTROLLED DISTRIBUTION NO. 53

FROM: LACBWR Plant Manager

8/9/2006

SUBJECT: Changes to LACBWR Controlling Documents

- I. The following document has been revised:

**LACBWR QUALITY ASSURANCE PROGRAM DESCRIPTION (QAPD),**  
Revision 20

**Instructions:**

Remove and replace Statement of Quality Assurance Policy.  
Remove and replace Table of Contents.  
Remove and replace all sections of the QAPD.

(Also included for information is the DPC transmittal letter with description of changes.)

**NOTE:** 10 CFR 50.54(a) allows for distribution of QAPD revisions without written NRC approval, after a 60-day waiting period. Since a time period of at least 60 days has elapsed since submittal of this revision, with no NRC response having been received, no acceptance letter is included with this distribution.

- ☒ The material listed above is transmitted herewith. Please verify receipt of all listed material, destroy superseded material, and sign below to acknowledge receipt.
- ☐ The material listed above has been placed in your binder.
- ☐ Please review listed material, notify your personnel of changes, and sign below to acknowledge your review and notification of personnel. [To be checked for supervisors for department specific procedures and LACBWR Technical Specifications.]
- ☐ The material listed above has been changed. [To be checked for supervisors when materials applicable to other departments are issued to them.]

/S/ \_\_\_\_\_ DATE \_\_\_\_\_

Please return this notification to the LACBWR Secretary within ten (10) working days.

A Touchstone Energy® Cooperative 

Q004

WILLIAM L. BERG  
President and CEO

COR-FILE:

LAC Q-1



May 23, 2006

In reply, please refer to LAC-13912

DOCKET NO. 50-409

Document Control Desk  
U. S. Nuclear Regulatory Commission  
Washington, D.C. 20555

SUBJECT: Dairyland Power Cooperative  
La Crosse Boiling Water Reactor (LACBWR)  
Possession-Only License No. DPR-45  
Quality Assurance Program Description

REFERENCES: (1) 10 CFR 50, Section 50.54(a)(3) and 50.4 (b)(7)  
(2) 10 CFR 50.71

In accordance with References (1) and (2), we are submitting Revision 20 of our Quality Assurance Program Description (QAPD).

Page change locations are indicated by a bold bar in the right-hand margin. The changes in this revision consist of the following:

- Title change throughout the Program, where applicable, from "QA Supervisor" to "QA Manager." Change in title only, no reporting differences. This results in the issuing of the entire program.
- Section 0.0  
Par. B, Terms and Definitions – add definition of Q1.
- Section IV  
Par. A, General – this paragraph revised to include the words "for Q1 systems" in the first sentence to clarify current requirements.

A Touchstone Energy® Cooperative 

▪ **Section IV**

Par. B, Responsibilities, item 2 – paragraph simplified by removing unnecessary language.

▪ **Section VII**

Par. E, Receiving Inspection, item 3 – wording clarification, administrative change only.

▪ **Figure 1**

On LACBWR organization chart – Revision number added to chart. “Regulatory Matters” changed to “Quality Assurance Matters” for DPC Manager Quality Assurance dotted line reporting to DPC President & CEO. This term better reflects the information that would be reported to the President & CEO and includes applicable regulatory matters.

▪ **Figure 2**


On DPC organization chart – Revision number added to chart.

All of the above described changes are administrative in nature and do not constitute a reduction in commitment to quality.

Please contact Don Egge (608-788-4000 or 787-1484) of my staff with any questions or comments you may have regarding this submittal.

Sincerely,

DAIRYLAND POWER COOPERATIVE



William L. Berg, President and CEO

WLB:DGE:dh

Enclosures

cc w/enc: James L. Caldwell, NRC Region III Administrator  
Kristina Banovac, NRC Project Manager

---

DAIRYLAND POWER COOPERATIVE  
LA CROSSE BOILING WATER REACTOR

**STATEMENT OF QUALITY ASSURANCE POLICY**

The Quality Assurance Program described herein has been developed by Dairyland Power Cooperative (DPC) to assure safe and reliable operation of the La Crosse Boiling Water Reactor (LACBWR) in a SAFSTOR condition. This program is designed to meet the requirements of Title 10 of the Code of Federal Regulations, Part 50, Appendix B, "Quality Assurance Criteria for Nuclear Power Plants and Fuel Reprocessing Plants," as it would apply to a possession-only condition.

The Quality Assurance Program applies to all activities affecting the functions of the structures, systems, and components that are associated with a possession-only license using a graded approach. These activities include design, operations, maintenance, repair, fuel handling, testing and modifications. Design and fabrication of shipping casks used for shipment of radioactive material will not be conducted under this Quality Assurance Program.

The DPC Manager, Quality Assurance, is responsible for the establishment of a Quality Assurance Program which meets the requirements of 10 CFR 50, Appendix B, and implementation of the program.

William L. Berg  
(President & CEO)

May 23, 2006  
(Date)

# QUALITY ASSURANCE PROGRAM DESCRIPTION

## TABLE OF CONTENTS

<u>SECTION</u>		<u>PAGE</u>
	STATEMENT OF POLICY	
0	INTRODUCTION .....	1
I.	ORGANIZATION .....	3
II.	QUALITY ASSURANCE PROGRAM .....	13
III.	DESIGN CONTROL AND REVIEW .....	15
IV.	PROCUREMENT DOCUMENT CONTROL .....	18
V.	INSTRUCTION, PROCEDURES AND DRAWINGS .....	20
VI.	DOCUMENT CONTROL .....	23
VII.	CONTROL OF PURCHASED MATERIAL, EQUIPMENT, AND SERVICES .....	25
VIII.	IDENTIFICATION AND CONTROL OF MATERIAL, PARTS, AND COMPONENTS .....	28
IX.	CONTROL OF SPECIAL PROCESSES .....	30
X.	INSPECTION .....	32
XI.	TEST CONTROL .....	34
XII.	CONTROL OF MEASURING AND TEST EQUIPMENT .....	37
XIII.	HANDLING, STORAGE, AND SHIPPING .....	39
XIV.	INSPECTION, TEST, AND OPERATING STATUS .....	41
XV.	NONCONFORMING MATERIALS, PARTS, OR COMPONENTS .....	43
XVI.	CORRECTIVE ACTION .....	45
XVII.	QUALITY ASSURANCE RECORDS .....	47
XVIII.	AUDITS .....	51
	TABLE I .....	53
	FIGURE 1 - FACILITY ORGANIZATION .....	54
	FIGURE 2 - OFFSITE ORGANIZATION .....	55



DAIRYLAND POWER COOPERATIVE  LACBWR  <b>QUALITY ASSURANCE PROGRAM DESCRIPTION</b>	SECTION 0.0	REV.NO. 20
	INTRODUCTION	
	DATE 05/15/06	PAGE 2 OF 2

B. Terms and Definitions

The definitions listed below are used frequently throughout this document.

COMPANY - Dairyland Power Cooperative (DPC)

LACBWR - La Crosse Boiling Water Reactor.

QUALITY ASSURANCE (QA) - All those planned and systematic actions necessary to provide adequate confidence that a structure, system, or component will perform satisfactorily in service.

QUALITY CONTROL (QC) - Those Quality Assurance actions which provide a means to control and measure the characteristics of an item, process or facility to established requirements.

ORC - Operations Review Committee.

FACILITY - Encompasses the site and facility systems which support a possession-only license (SAFSTOR) condition, but excludes electric power transmission apparatus located beyond the site switchyard.

PLANT PROCEDURE - A document describing the manner of conducting an action or process.

ADMINISTRATIVE CONTROL PROCEDURE (ACP) - A document which establishes the guidelines and requirements governing functional activities (i.e., Administration, Material Request, Control Room Log, etc.).

QUALITY ASSURANCE INSTRUCTION (QAI) - A document which establishes the guidelines and requirements governing quality assurance and control activities.

QA MANUAL - Manual comprised of the QA Program Description.

SRC - Safety Review Committee.

QUALITY ASSURANCE PROCEDURE (QUA) - A document which establishes the guidelines and requirements governing the Generation Division quality-related activities.

SCHEDULE INTERVAL - A time frame that a scheduled activity shall be performed within, with a maximum allowable extension not to exceed 25 percent of the schedule interval.

Q1 - Any item or component within the FSW System and Fuel Handling System.





<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION 1	REV. NO. 20
	ORGANIZATION	
	DATE 05/15/06	PAGE 2 OF 10

The Plant Manager has complete overall technical and administrative control over the groups designated in the organizational chart for the facility.

The Plant Manager directly supervises and coordinates all activities related to possession-only operation and maintenance of the facility through the Shift Supervisors and coordinates the activities of the maintenance departments. The Plant Manager ensures that regular inspections of the facility are performed, and he is responsible for the review of all log sheets, malfunction reports, surveillance, and maintenance records. The Plant Manager is concerned with the detailed operation and maintenance of the facility. The Plant Manager enforces all facility operating and safety procedures and ensures that approved operating and maintenance procedures are followed.

4. Training Supervisor reports directly to the Plant Manager and has responsibility for establishing and implementing a training and requalification program for operators in accordance with applicable regulations.
5. Security Supervisor reports directly to the Plant Manager, with access to the DPC President & CEO if necessary for security matters, and is responsible for implementation and administration of the LACBWR Physical Security Program. The Security Supervisor is responsible for the day-to-day administration of the security organization.
6. Manager, Quality Assurance (QA) reports directly to the Director, Generation Support Services, with access to the DPC President & CEO if necessary for regulatory matters. He has responsibility for establishing a quality assurance program and performing audits of the program to determine its effectiveness. The Manager, QA, has the authority to stop fabrication, installation, or testing of structures, systems, or components that do not conform to specifications or approved procedures.
7. Quality Assurance Department Personnel report directly to the Manager, QA, and are responsible for assuring that the activities required by the QA Program are implemented.
8. Director, Generation Support Services, reports directly to the VP, Generation Division, and has corporate oversight of the QA Department.

<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION I	REV. NO. 20
	ORGANIZATION	
	DATE 05/15/06	PAGE 3 OF 10

9. Administrative Assistant reports directly to the Plant Manager and is responsible for maintenance of LACBWR's QA records, procedures, and indexes.
10. Administrative Secretary reports directly to the Administrative Assistant and is responsible for assisting in the maintenance of LACBWR's QA records, procedures, and indexes.
11. Technical Support Staff consists of on-site engineers (Technical Support and Reactor/Radiation Protection) and off-site engineers, covering various disciplines, and/or contractors whose services are deemed necessary, all responsible to the Plant Manager. They provide technical services to the Plant Manager in areas of licensing, analyzing test results, design changes, and may, as requested, perform audits to provide assurance that facility activities are being performed consistent with approved procedures and licensing provisions.
12. Instrument Department Personnel report directly to the Plant Manager and are responsible for the calibration, testing, maintenance, and modifications of LACBWR's plant instrument systems and components.
13. Mechanical Maintenance Department Personnel report directly to the Plant Manager and are responsible for the maintenance and modification of LACBWR's plant mechanical systems and components.
14. Electrical Maintenance Department Personnel report directly to the Plant Manager and are responsible for the testing, maintenance and modification of LACBWR's plant electrical systems and components.
15. Health and Safety Supervisor reports directly to the Plant Manager and is responsible for the administration, maintenance, and implementation of the Radioactive Waste Program, Plant Chemistry Program, Radiation Protection Program, and Environmental Monitoring Program.
16. Health Physics Personnel report directly to the Health and Safety Supervisor and are responsible to adhere to the requirements of the Radioactive Waste Program, Plant Chemistry Program, Radiation Protection Program, and Environmental Monitoring Program.

DAIRYLAND POWER COOPERATIVE  LACBWR  <b>QUALITY ASSURANCE PROGRAM DESCRIPTION</b>	SECTION I	REV. NO. 20
	ORGANIZATION	
	DATE 05/15/06	PAGE 4 OF 10

17. Shift Supervisors report directly to the Plant Manager and are responsible for the safe operation of the facility when on shift and for maintaining complete control of all activities performed on shift and ensuring that all operations are conducted safely and according to approved procedures and specifications.
18. Fuel Handlers report directly to the Shift Supervisor and are responsible for safe operation of LACBWR plant components and systems to support safe storage of spent fuel.
19. Fire Protection Supervisor reports directly to the Plant Manager and is responsible for the administration and implementation of LACBWR's fire protection program.
20. The Operations Review Committee is an advisory committee to the Plant Manager. They review facility operations and verify implementation of site quality assurance practices. Minutes of ORC meetings are distributed to the Safety Review Committee.
  - a. The Operations Review Committee shall function to advise the Plant Manager on all matters related to nuclear safety.
  - b. The Operations Review Committee shall be composed of the following:

Chairman: Plant Manager  
Members: LACBWR Management and Engineering Staff
  - c. ORC members shall meet minimum qualifications as specified in Technical Specification 6.3.
  - d. All alternate members shall be appointed in writing by the ORC Chairman to serve on a temporary basis; however, no more than two alternates shall participate as voting members in ORC activities at any one time.
  - e. The ORC shall meet at least once per calendar quarter and as convened by the ORC Chairman or his designated alternate.
  - f. The minimum quorum of the ORC necessary for the performance of the ORC responsibility and authority provisions shall consist of the Chairman, or his designated alternate, and three (3) members, including alternates.

<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION 1	REV. NO. 20
	ORGANIZATION	
	DATE 05/15/06	PAGE 5 OF 10

g. The Operations Review Committee shall be responsible for:

- 1) Review of [1] all procedures required by Section V of this Program and changes thereto, [2] any other proposed procedures or changes thereto as determined by the Plant Manager to affect nuclear safety.
- 2) Review of all proposed tests and experiments that affect nuclear safety.
- 3) Review of all proposed changes to the Appendix "A" Technical Specifications.
- 4) Review of all proposed changes or modifications to facility systems or equipment that affect nuclear safety.
- 5) Investigation of all violations of the Technical Specifications including the preparation and forwarding of reports covering evaluation and recommendations to prevent recurrence to the President & CEO and to the Safety Review Committee (SRC).
- 6) Review of all REPORTABLE EVENTS.
- 7) Review of facility operations to detect potential nuclear safety hazards.
- 8) Performance of special reviews, investigations or analyses and reports thereon as requested by the Plant Manager or SRC.
- 9) Review of the Contingency Plan, the Plant Security Plan, and implementing procedures.
- 10) Review of the Emergency Plan and implementing procedures.
- 11) Review of the Process Control Program (PCP).
- 12) Review of the Decommissioning Plan.
- 13) Review of the Training Plan and implementing procedures.
- 14) Review of the Offsite Dose Calculation Manual (ODCM).
- 15) Review of the Fire Protection Program and implementing procedures.

<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION I	REV. NO. 20
	ORGANIZATION	
	DATE 05/15/06	PAGE 6 OF 10

h. The ORC shall:

- 1) Recommend in writing to the Plant Manager approval or disapproval of items considered under g (1) through (15) above.
- 2) Render determinations in writing with regard to whether or not each item considered under g (1) through (4) above requires a license amendment.
- 3) Provide written notification within 24 hours to the President & CEO and the SRC of disagreement between the ORC and the Plant Manager; however, the Plant Manager shall have responsibility for resolution of such disagreements.

i. The ORC shall maintain written minutes of each ORC meeting that, at a minimum, document the results of all ORC activities performed under the responsibility and authority provisions. Copies shall be provided to the President & CEO and the SRC.

21. The Safety Review Committee is an advisory committee responsible to the President & CEO for independent reviews and audits to verify that the facility is being maintained consistent with company safety, administrative, and licensing provisions.

- a. The SRC shall function to provide independent review and audit of aspects of plant nuclear safety.
- b. The SRC shall be composed of a Chairman and a minimum of three members who are appointed by either the DPC President & CEO or the VP, Generation. The Chairman shall be appointed by the President & CEO. In addition, the Plant Manager is also a member of the SRC. SRC members appointed by the President & CEO or VP, Generation, shall not be members of the plant staff.
- c. All SRC alternate members shall be appointed in writing by the DPC President & CEO or VP, Generation, to serve on a temporary basis; however, no more than two alternates shall participate as voting members in SRC activities at any one time.

<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION I	REV. NO. 20
	ORGANIZATION	
	DATE 05/15/06	PAGE 7 OF 10

- d. Membership to the SRC requires that an individual meet one or more of the academic and/or experience requirements listed below. The majority of the SRC members shall meet the requirements of No. (1).
- 1) Bachelor Degree in Engineering or the physical sciences, plus five years' total experience in one or more of the below listed disciplines.
  - 2) Nine years' combined total experience in one or more of the below listed disciplines.
    - Nuclear Power Plant Technology
    - Facility Operations
    - Power Plant Design
    - Engineering/Nuclear Engineering
    - Radiation Safety
    - Safety Analysis
    - Instrumentation and Control
    - Quality Assurance
- e. Consultants shall be utilized, as determined by the SRC Chairman, to provide expert advice to the SRC.
- f. The SRC shall meet at least once per year, and as deemed necessary by the SRC Chairman or the Plant Manager.
- g. The minimum quorum of the SRC necessary for the performance of the SRC review and audit functions shall consist of the Chairman, or his designated alternate, and at least three SRC members, including alternates. No more than a minority of the quorum shall have line responsibility for the facility.

<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION I	REV. NO. 20
	ORGANIZATION	
	DATE 05/15/06	PAGE 8 OF 10

h. The SRC shall review:

- 1) Evaluations performed by plant staff, pursuant to 10 CFR 50.59, where a determination has been that a license amendment is not required.
- 2) Proposed license amendments prior to submittal to the NRC.
- 3) Proposed changes to Appendix "A" Technical Specifications.
- 4) Violations of codes, regulations, orders, Technical Specifications, license requirements, or of internal procedures or instructions having nuclear safety significance.
- 5) Significant deviations from normal and expected performance of facility equipment that affects nuclear safety.
- 6) ALL REPORTABLE EVENTS.
- 7) All recognized indications of an unanticipated deficiency in some aspect of design or operation of structures, systems, or components that could affect nuclear safety.
- 8) Reports and meeting minutes of the ORC.
- 9) Changes to the Contingency Plan and Plant Security Plan.
- 10) Changes to the Emergency Plan.
- 11) Changes to the Decommissioning Plan.
- 12) Changes to the Offsite Dose Calculation Manual.
- 13) Changes to the Process Control Program.
- 14) Changes to the Quality Assurance Program Description.

<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION I	REV. NO. 20
	ORGANIZATION	
	DATE 05/15/06	PAGE 9 OF 10

- i. The following audits of facility activities shall be performed by the Quality Assurance Department or a qualified off-site entity under the cognizance of the SRC. These audits shall encompass:
  - 1) The conformance of facility operation to provisions contained within the Appendix "A" Technical Specifications and applicable license conditions at least once per 24 months.
  - 2) The performance, training and qualifications of the entire facility staff at least once per 24 months.
  - 3) The results of actions taken to correct deficiencies occurring in facility equipment, structures, systems or method of operation that affect nuclear safety at least once per 12 months.
  - 4) The performance of activities required by the Quality Assurance Program to meet the criteria of Appendix "B", 10 CFR 50, at least once per 24 months.
  - 5) The Emergency Plan and implementing procedures at least once per 12 months.
  - 6) The Contingency Plan, the Security Plan and implementing procedures, at least once per 12 months.
  - 7) The Fire Protection Program and implementing procedures at least once per 24 months.
  - 8) A fire protection and loss prevention inspection and audit shall be performed at least once per 24 months.
  - 9) The ODCM and Radiological Environmental Monitoring Program and results at least once per 12 months.
  - 10) The Radiation Protection Program and the Process Control Program, and implementing procedures, at least once per 12 months.
  - 11) Any other area of facility operation considered appropriate by the SRC or the President & CEO.



<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION 1	REV. NO. 20
	ORGANIZATION	
	DATE 05/15/06	PAGE 10 OF 10

- j. The SRC shall report to and advise the President & CEO on those areas of responsibility listed in paragraphs 21.h and 21.i.
- k. Records of SRC activities shall be prepared, approved and distributed as indicated below:
  - 1) Minutes of each SRC meeting shall be prepared, approved and forwarded to the President & CEO within 20 days following each meeting.
  - 2) Audit reports encompassed by paragraph 21.i above, shall be forwarded to the President & CEO and to the management positions responsible for the areas audited within 30 days after completion of the audit.

**B. Facility Organization Requirements**

- 1. The facility organization includes one or more individuals trained in the various disciplines as noted in Figure 1.
- 2. Job descriptions have been provided for all personnel of the LACBWR staff. The job descriptions identify the authority and responsibility that are associated with the position.

**C. Dairyland Power Cooperative Organization**

Figure 2 shows the organization structure for Dairyland Power Cooperative. The LACBWR facility is a responsibility of the President & CEO. The Procurement Department has responsibility for all purchases as they apply to all generating stations, including LACBWR, and responsibility for control, identification, and issuance of all materials, parts, and components. Procurement is the responsibility of the VP, Finance and Administration.



<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION II	REV. NO. 20
	<b>QUALITY ASSURANCE PROGRAM</b>	
	DATE 05/15/06	PAGE 2 OF 2

**B. Applicability**

The LACBWR QA Program is based on the requirements of 10 CFR 50, Appendix B, "Quality Assurance Requirements for Nuclear Power Plants," and Regulatory Guide 1.33 which addresses the applicable requirements of ANSI N18.7-1976, "Administrative Controls and Quality Assurance for the Operational Phase of Nuclear Power Plants," as they apply to a possession-only license.

**C. Implementation**

Individuals assigned responsibilities, as discussed under "ORGANIZATION," shall prepare administrative and quality assurance procedures as necessary to implement the requirements of this program. Procedures shall include appropriate quantitative and qualitative acceptance criteria necessary to determine that the activity is being properly performed. Audit reports are distributed to DPC management for their review and assessment of the QA Program, as to effectiveness, scope, adequacy, and implementation. Indoctrination in the QA Program requirements shall be provided to all facility personnel performing activities which could affect the quality of components, systems, or structures.



<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION III	REV. NO. 20
	<b>DESIGN CONTROL AND REVIEW</b>	
	DATE 05/15/06	PAGE 2 OF 3

4. The Operations Review Committee is responsible for reviewing all proposed facility changes and recommending approval or disapproval to the Plant Manager. The review shall determine whether the proposed modifications involve any License Amendment Request or a possible change in the Technical Specifications.
5. The Plant Manager is responsible for reviewing the recommendations of the Operations Review Committee and taking appropriate action. He shall refer any License Amendment Request to the Safety Review Committee.
6. The Safety Review Committee is responsible for providing an independent review of facility changes. They shall provide assurance that the facility modification meets the design bases, regulatory requirements, and applicable codes and standards.

C. Requirements

1. A Facility Change shall be initiated for all modifications to structures, systems, and components important to safety and systems maintained operational during SAFSTOR. Facility Changes may be initiated by any knowledgeable person.
2. A control procedure shall be used for all modifications to systems determined no longer necessary for SAFSTOR.
3. Design bases, regulatory requirements, and applicable codes and standards shall be delineated for all proposed plant modifications to structures, systems, and components important to safety and systems maintained operational during SAFSTOR. These conditions shall be incorporated into drawings, specifications, procurement documents, and procedures by the job coordinator. The Quality Assurance Department shall specify appropriate quality standards.

<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION III	REV. NO. 20
	<b>DESIGN CONTROL AND REVIEW</b>	
	DATE 05/15/06	PAGE 3 OF 3

4. The Facility Change procedure shall describe and control design changes to structures, systems, and components important to safety and systems maintained operational during SAFSTOR, from concept through final approval, distribution, and implementation of the change. The procedure shall provide for the review of stress, hydraulic, thermal, and accident analyses, compatibility of materials, maintenance, test, and repair as appropriate. The procedure shall provide for a design review by an engineer or other qualified individual other than the one who performed the design.
5. All proposed modifications shall be reviewed to determine whether they require a License Amendment Request.



<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE PROGRAM DESCRIPTION</b>	SECTION IV	REV. NO. 20
	<b>PROCUREMENT DOCUMENT CONTROL</b>	
	DATE 05/15/06	PAGE 2 OF 2

**C. Requirements**

1. Purchase requisitions for new material, equipment, and services and for spare or replacement parts shall be initiated by any department personnel. The purchase requisition shall contain the information such as quantity, item description, and technical and quality requirements necessary for procurement of the item.
2. Purchase orders shall include specifications that contain all the information necessary to assure material, equipment, and services are of adequate quality. This shall include material selection, design data, equipment description, source inspection and testing requirements, cleaning and packaging requirements, and required documentation as deemed necessary.
3. Documentation required to provide evidence that materials, equipment, and services are of adequate quality shall be clearly delineated in purchase orders. This shall include a listing of each item of documentation to be submitted, when it is to be submitted, what requires approval prior to manufacture, and to whom it shall be submitted.
4. To the extent necessary, procurement documents shall require suppliers of material, equipment, and services to have a quality assurance program complying with the pertinent provisions of 10 CFR 50, Appendix B. Suppliers shall be required to provide DPC access to their facilities and records for inspection and audit, as required, to determine compliance with provisions of the purchase order. These requirements shall extend to lower tier procurements, as determined by DPC management.
5. Purchase requisitions and engineering specifications shall be reviewed by the Quality Assurance Department to assure that all necessary technical and quality requirements are included or referenced.
6. Formal purchase orders that have been prepared from the purchase requisition shall be reviewed to assure all required information is correctly incorporated.
7. Changes in technical content in procurement documents shall be initiated and reviewed in accordance with the same procedures utilized in preparation of the original document. The Plant Manager's approval is required prior to any changes being implemented to previously approved quality control orders.





<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION V	REV. NO. 20
	<b>INSTRUCTIONS, PROCEDURES, AND DRAWINGS</b>	
	DATE 05/15/06	PAGE 2 OF 3

C. Requirements

1. Detailed instruction for possession-only operation of the plant shall be contained in procedures and checklists covering the following activities:
  - a. administrative control,
  - b. general system operation,
  - c. startup, operation, and shutdown of systems,
  - d. correction of abnormal, off-normal, or alarm conditions,
  - e. control of emergencies and other significant events,
  - f. radioactivity control,
  - g. chemical and radiochemical control,
  - h. Security Plan implementation,
  - i. quality assurance,
  - j. fuel handling,
  - k. surveillance and test activities of equipment,
  - l. Emergency Plan implementation,
  - m. Fire Protection Program implementation,
  - n. Process Control Program implementation,
  - o. Offsite Dose Calculation Manual implementation, or
  - p. any other procedures required by Regulatory Guide 1.33, Revision 2, for a possession-only condition.

<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE PROGRAM DESCRIPTION</b>	SECTION V	REV. NO. 20
	<b>INSTRUCTIONS, PROCEDURES, AND DRAWINGS</b>	
	DATE 05/15/06	PAGE 3 OF 3

2. For activities other than those within normal craft expertise, instructions for maintenance and repair shall be contained in procedures. These procedures shall contain instructions for preparation, performance, testing, and return to service. The procedures may reference manufacturer's instruction manuals, drawings, and other sources, as applicable.
3. Instructions, procedures, or drawings shall delineate methods and sequences when an activity is to be performed. These documents shall include appropriate quantitative or qualitative acceptance criteria for determining that the activity has been satisfactorily performed.
4. The department responsible for an activity shall be required to provide the necessary internal review and approval of instructions, procedures, or drawings prior to performing the activity.
5. Changes to or deviations from established instructions, procedures, or drawings will require the same review and approval as the original document. However, temporary changes to procedures that do not change the intent of the original procedure may be made in ink, dated, and approved by two people of the facility management staff. Such changes shall be documented and reviewed by the ORC and approved by the Plant Manager within 30 days of implementation.
6. Applicable sections of the appropriate procedures shall be followed in the review, processing of changes or deviations, filing, and distribution of procedures, drawings, and specifications.
7. Procedures will be reviewed periodically as set forth in administrative procedures.



<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	<b>SECTION VI</b>	<b>REV. NO. 20</b>
	<b>DOCUMENT CONTROL</b>	
	<b>DATE 05/15/06</b>	<b>PAGE 2 OF 2</b>

**C. REQUIREMENTS**

1. Procedures shall be established for the issuance of procedures, drawings, and specifications. A document control procedure shall be prepared to provide a uniform system of document identification.
2. All documents shall have an identification number, title, date, and revision number. Documents shall be filed and controlled by use of this identification. Each type of document shall be filed in a central location identified in a document control procedure.
3. Drawings, specifications, and procedures, including revisions, shall be reviewed for adequacy and approved for release by authorized personnel. The required reviews and approvals shall be specified in a document control procedure.
4. The Administrative Assistant shall assure that current documents are distributed to and used at the location where the prescribed activity is performed. Documents and revisions shall be distributed as specified in a document control procedure. Preliminary and superseded documents shall be clearly identified and closely controlled to preclude their misuse.
5. An index of each type of document shall be established and maintained to provide the current status of documents.



<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE PROGRAM DESCRIPTION</b>	SECTION VII	REV. NO. 20
	CONTROL OF PURCHASED MATERIAL, EQUIPMENT, AND SERVICES	
	DATE 05/15/06	PAGE 2 OF 3

2. Suppliers of casks used for shipment and storage of radioactive material shall be evaluated to ensure that the design and fabrication of packaging are performed under the control of an NRC-approved QA Program.

**D. Source Inspection**

1. When appropriate, suppliers shall be requested to furnish DPC with sufficient information concerning their manufacturing and inspection plan to permit DPC or their designated agent to plan and implement a source inspection plan.
2. When appropriate, inspection plans shall include witness and hold points for inspection of items, witnessing of processes or tests, audit of required quality documentation, and verification that vendors have complied with the specification requirements and have documented any deviation from the specifications.

**E. Receiving Inspection**

1. Items shall be examined by Materials Management personnel upon receipt for shipping damage, correctness of identification, and specified quality documentation, in accordance with approved instructions.
2. Documentary evidence attesting that items conform to purchase order requirements shall be available at the plant prior to installation or use of the item.
3. Documentary evidence shall be sufficient to identify that specific requirements such as codes, standards, and specifications are met by the purchased item. This requirement shall be satisfied by having available at the plant, copies of the purchase order and appropriate documents referenced therein.
4. All QC ordered materials, parts, and components will be segregated upon receipt and will be placed in a receiving inspection hold area separate from storage facilities. After acceptance, the material will be stamped as acceptable and placed in specified spare parts storage.

<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION VII REV. NO. 20	
	CONTROL OF PURCHASED MATERIAL, EQUIPMENT, AND SERVICES	
	DATE 05/15/06	PAGE 3 OF 3

5. During receiving inspection, if a nonconformance or discrepancy exists, the material shall be placed on hold and will remain in a hold status until final disposition is determined. A Discrepancy Report shall be initiated.
6. Items dispositioned as unacceptable for use shall be rejected and removed from the controlled receiving inspection area.





<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION VIII	REV. NO. 20
	IDENTIFICATION AND CONTROL OF MATERIAL, PARTS, AND COMPONENTS	
	DATE 05/15/06	PAGE 2 OF 2

2. Specifications shall require that materials, parts, and components are identified in accordance with purchase order numbers and shall require that documentation have identification providing traceability to the item.
3. Physical identification by purchase order number shall be used to the maximum extent possible for relating an item at any time to applicable documentation. Identification shall be either on the item or records traceable to the item. Where physical identification is impractical, physical separation, procedural control, or other appropriate means shall be employed.



<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION IX	REV. NO. 20
	<b>CONTROL OF SPECIAL PROCESSES</b>	
	DATE 05/15/06	PAGE 2 OF 2

**C. Requirements**

1. Welding, heat treating, cleaning or decontamination of parts, and non-destructive examination shall be accomplished under controlled conditions in accordance with applicable codes, standards, criteria, and other special requirements, using qualified personnel and procedures. Qualification of personnel and procedures shall comply with the requirements of applicable codes and standards.
2. Welders and welding procedures shall be qualified, as appropriate, in accordance with Section IX of the ASME Boiler and Pressure Vessel Code and/or AWS D1.1 American Welding Society Structural Welding Code. Records of the test results obtained in welding procedures and welder performance qualifications and a listing of qualified personnel and procedures shall be maintained.
3. Non-destructive examination personnel shall be qualified in accordance with the American Society for Non-destructive Testing Standard SNT-TC-1A. Records of training, test results, and a listing of qualified personnel shall be maintained.
4. Plant procedures shall be established to describe the requirements for qualification of personnel and procedures.
5. Procedures shall be established to describe the method used to control the receipt, storage, baking, drying, and disbursal of welding filler metals.
6. Equipment used for accomplishing special processes shall be calibrated, maintained, stored, handled, and issued in accordance with applicable procedures.



<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION X	REV. NO. 20
	INSPECTION	
	DATE 05/15/06	PAGE 2 OF 2

2. Mandatory inspection hold points, which require witnessing or inspecting of an activity before proceeding, shall be indicated in the appropriate procedures or specifications. The inspection shall be documented to indicate approval and release prior to continuation of the activity.
3. Inspection requirements shall apply to all activities whether performed by company personnel or contractor personnel, and shall require that inspection procedures and instructions, along with necessary drawings, are provided prior to commencing inspection activities.
4. Inspection requirements governing modifications, repairs, and replacement shall be in accordance with the original design and inspection requirements or as amended by approved changes to the original design.



<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION XI	REV. NO. 20
	TEST CONTROL	
	DATE 05/15/06	PAGE 2 OF 3

5. The Operations Review Committee is responsible for review of all proposed test procedures, special testing procedures, performance testing procedures following facility modification, and 50.59 reviews.
6. The Safety Review Committee is responsible for reviewing 50.59 evaluations to verify that such tests did not require a license amendment, and for reviewing proposed test activities that involve a License Amendment Request, prior to submittal to the NRC.

C. Requirements

1. A program shall be established to assure all testing required to demonstrate that structures, systems, and components will perform satisfactorily in service is identified and documented.
2. Testing shall be performed in accordance with approved test procedures that incorporate or reference the requirements and acceptance criteria contained in applicable design documents and Technical Specifications.
3. Test procedures shall incorporate, but not be limited to, requirements for such items as: hold points, witness points, caution notes, emergency requirements, and test jumper logs.
4. Test procedures shall include, as a minimum, provisions for assuring that:
  - a. Prerequisites have been completed that include, as a minimum:
    - 1) Control of systems status as necessary.
    - 2) Availability of calibrated instrumentation and special equipment.
  - b. Test objectives and applicable acceptance limits are stated.
  - c. Test results are documented.
  - d. Detailed instructions for performing the test are included.
  - e. Test results are reviewed and approved.



<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION XI      REV. NO. 20	
	TEST CONTROL	
	DATE 05/15/06	PAGE 3 OF 3

5. Test reports shall include identification of the inspector, individual conducting the test, the data recorder, the type of observation made, the equipment used, the test results, the acceptability of the test results, and approved disposition for any deviations.

Test results which fail to meet the requirements and acceptance criteria shall be properly noted and appropriate corrective action taken.



<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE PROGRAM DESCRIPTION</b>	<b>SECTION XII</b>	<b>REV. NO. 20</b>
	<b>CONTROL OF MEASURING AND TEST EQUIPMENT</b>	
	<b>DATE 05/15/06</b>	<b>PAGE 2 OF 2</b>

2. To assure equipment accuracy, inspection, measuring, and test equipment shall be controlled, calibrated, adjusted, and maintained periodically, or prior to use. Calibrations are performed against certified measurement standards that are traceable to nationally recognized standards. Where national standards do not exist, provisions will be established to document the basis for calibration. Control measures and procedures shall prevent the use of calibrated tools, gauges, instruments, and other measuring and test equipment by unauthorized personnel. Special calibration and control measures are not required for devices when normal commercial practices provide adequate accuracy.
3. When an item of measuring and test equipment is found to be out of calibration, an investigation will be conducted and documented to determine the validity of previous inspections, tests, or calibrations which were performed with the use of that item.
4. Records or logs of the calibration history of measuring and test equipment shall be maintained.
5. Measuring and test equipment shall be controlled by a permanently affixed serial number. Calibration decals, tags or stickers shall be displayed prominently on each device and shall reflect the date of calibration, due date of the next calibration (for recurring calibration) and identity of person performing the calibration.



<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	<b>SECTION XIII</b>	<b>REV. NO. 20</b>
	<b>HANDLING, STORAGE AND SHIPPING</b>	
	<b>DATE 05/15/06</b>	<b>PAGE 2 OF 2</b>

4. Specifications and procedures establish the requirements for special handling tools and equipment to ensure safe and adequate handling of critical, sensitive, or radioactive items.
5. Special handling tools and equipment will be inspected and tested in accordance with approved procedures, at specified intervals, to verify that tools and equipment are adequately maintained.
6. Materials and equipment will normally be handled by materials handling personnel. Fuel and other special shipments which require special equipment and handling will be handled by others knowledgeable and/or specially trained personnel. The proper use of fuel handling equipment will be described in fuel handling procedures.
7. Storage of material and equipment will be in areas free from fumes, vapors, and dust. Storage will be in areas protected from the weather, as appropriate, and in which chemical storage is excluded, except as may be specifically authorized in writing. Storage will be in areas which satisfy the handling and storage requirements specified for the item.



<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION XIV	REV. NO. 20
	INSPECTION, TEST, AND OPERATING STATUS	
	DATE 05/15/06	PAGE 2 OF 2

3. Structures, systems, and components that are found to be unacceptable during or after testing shall be clearly identified in the Shift Supervisor's Log Book or on the Test Data Sheets.
4. Operations involving handling of fuel assemblies or other radioactive sources shall be identified and controlled by the use of tags, control log sheets, or other suitable means.
5. Facility maintenance, repair, or modification of components, systems, or structures will utilize a test sheet or Shift Supervisor log entry to indicate its acceptance or rejection for a particular component, system, or structure.
6. Maintenance Requests shall be used to originate, approve, authorize, and document all non-routine maintenance or repair work performed at LACBWR.





<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION XV	REV. NO. 20
	<b>NONCONFORMING MATERIALS, PARTS, OR COMPONENTS</b>	
	DATE 05/15/06	PAGE 2 OF 2

3. Deficiencies which cannot be corrected by the vendor shall be reviewed by the Engineering Staff. The Engineering Staff will recommend repair, rework, accept, or reject. Items shall be repaired or reworked only in accordance with approved procedures and shall be re-inspected after repair by the QA Department. QA shall ensure that documented and approved procedures are available prior to repair or rework and shall re-inspect all repaired or reworked items.

Items which are accepted for use with a known deficiency shall be fully documented with the specification requirement, justification for acceptance, and effect of such use. All such items shall be approved by the Plant Manager prior to use.



<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION XVI	REV. NO. 20
	<b>CORRECTIVE ACTION</b>	
	DATE 05/15/06	PAGE 2 OF 2

2. Conditions adverse to quality which involve design deficiencies, or recommended corrective actions that involve a design change, shall be reviewed by the Engineering Staff.
3. Nonconforming materials, parts, or components shall be identified by a Deficiency Report. A Deficiency Report shall be initiated and processed whenever the actual condition is not in accordance with drawings or specifications. Corrective action is an integral part of the nonconforming control system.
4. Maintenance Requests can be a part of the documented corrective action program.
5. Quality Assurance Department shall audit corrective actions to assure that the cause of the condition has been determined and that corrective action has been taken in accordance with recommendations.



<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE PROGRAM DESCRIPTION</b>	SECTION XVII	REV. NO. 20
	<b>QUALITY ASSURANCE RECORDS</b>	
	DATE 05/15/06	PAGE 2 OF 4

**D. System Requirements**

1. A system shall be established to identify all documents that must be kept permanently (lifetime records). An index of non-permanent records shall be established.
2. An approved document listing will be reviewed on a regular basis to verify that the record file contains the latest revisions of all required documents.
3. A system will be established to control the issuance and return of all records.
4. The Operations Review Committee shall maintain written minutes of each ORC meeting that, at a minimum document the results of all ORC activities. Copies shall be provided to the President & CEO and the SRC.
5. Records of SRC activities shall be prepared, approved and distributed as indicated below:
  - a. Minutes of each SRC meeting shall be prepared, approved and forwarded to the President & CEO within 20 days following each meeting.

<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION XVII	REV. NO. 20
	<b>QUALITY ASSURANCE RECORDS</b>	
	DATE 05/15/06	PAGE 3 OF 4

**E. Record Retention**

In addition to the applicable record retention requirements of Title 10, Code of Federal Regulations, the following records shall be retained for at least the minimum period indicated.

1. The following records shall be retained for at least five years:
  - a. Records and logs of facility operation.
  - b. Records and logs of principal maintenance activities, inspections, repair and replacement of principal items of equipment related to nuclear safety.
  - c. All REPORTABLE EVENTS submitted to the Commission.
  - d. Records of surveillance activities, inspections, and calibrations required by the QAPD.
  - e. Records of changes made to the procedures required by Section V of the QAPD.
  - f. Records of radioactive shipments.
  - g. Records of sealed source and fission detector leak tests and results.
  - h. Records of annual physical inventory of all sealed source material of record.
  - i. QA Audits.
2. The following records shall be retained for the duration of the LACBWR License:
  - a. Facility design modification packages.
  - b. Records of new and irradiated fuel inventory, fuel transfers and assembly burn-up histories.
  - c. Records of radiation exposure for all individuals entering radiation control areas.

<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION XVII	REV. NO. 20
	QUALITY ASSURANCE RECORDS	
	DATE 05/15/06	PAGE 4 OF 4

- d. Records of gaseous and liquid radioactive material released to the environs, and records of analyses required by the Radiological Environmental Monitoring Program.
- e. Records of reactor tests and experiments.
- f. Records of training and qualification for current members of the facility staff.
- g. Records of in-service inspections performed pursuant to Technical Specifications.
- h. Records of reviews performed for changes made to procedures or equipment or reviews of tests and experiments pursuant to the LACBWR Decommissioning Order dated Aug. 7, 1991, as modified Sept. 15, 1994, and 10 CFR 50.59.
- i. Records of meetings of the ORC and the SRC.
- j. Records of Decommissioning and/or Dismantlement of the facility.





<b>DAIRYLAND POWER COOPERATIVE</b>  <b>LACBWR</b>  <b>QUALITY ASSURANCE</b> <b>PROGRAM DESCRIPTION</b>	SECTION XVIII	REV. NO. 20
	AUDITS	
	DATE 05/15/06	PAGE 2 OF 2

5. Quality Assurance Auditors shall assess the following:
  - a. evaluation of quality assurance practices, procedures, and instructions;
  - b. effectiveness of implementation; and
  - c. conformance with approved procedures.
6. A system of planned and scheduled audits shall be generated. All planned and scheduled audits shall be performed within their schedule interval.
7. In addition, audits shall be conducted on an unscheduled basis, when one or more of the following conditions exist:
  - a. When significant changes are made in functional areas of the Quality Assurance Program, including significant reorganizations and procedural revisions.
  - b. When it is suspected that safety, performance, or reliability of an item is questionable due to deficiencies or nonconformances in the Quality Assurance Program.
  - c. When a systematic, independent assessment of program effectiveness or item quality, or both, is considered necessary.
  - d. When it is considered necessary to verify the implementation of required corrective actions.
8. Deficiencies or nonconformances identified during an audit shall be documented and brought to the attention of the Plant Manager. Follow-up shall be performed to verify that corrective actions have been taken to correct the deficiencies or nonconformances.
9. Audit reports are sent to DPC management for their review and assessment of the QA Program.
10. Audit reports shall be forwarded to the President & CEO, and to the management positions responsible for the areas audited, within 30 days after completion of the audit.

TABLE 1

LACBWR QUALITY ASSURANCE PROGRAM (SECTION)	REGULATORY GUIDE 1.33		
	IMPLEMENTING PROCEDURES	ANSI 18.7 (SECTION)	10 CFR 50 APPENDIX B (SECTION)
0.0 INTRODUCTION			
I. ORGANIZATION	ACP-02.1, ACP-03.1	1, 3.1, 3.2, 3.4.2	I
II. QUALITY ASSURANCE PROGRAM	ACP-03.1, QAI-1	3.1, 3.2, 3.3, 3.4.2, 5.1, 5.2	II
III. DESIGN CONTROL AND REVIEW	ACP-04.1, ACP-03.3, ACP-04.3	5.2.7.2	III
IV. PROCUREMENT DOCUMENT CONTROL	ACP-05.1	5.2.13.1	IV, V, VI
V. INSTRUCTIONS, PROCEDURES, AND DRAWINGS	LACBWR OPERATING MANUAL, ACP-06.1, ACP-06.2	5.2.7, 5.3	V
VI. DOCUMENT CONTROL	ACP-06.1, 06.3, 07.1, 07.3, ECP-2, QAI-2, QAI-3	5.2.15	VI
VII. CONTROL OF PURCHASED MATERIAL, EQUIPMENT, AND SERVICES	ACP-08.2, ACP-08.4, QUA-006, 007	5.2.13.2	VII, VIII
VIII. IDENTIFICATION AND CONTROL OF MATERIALS, PARTS, & COMPONENTS	ACP-09.1, ACP-30.1	5.2.13.3	VIII
IX. CONTROL OF SPECIAL PROCESSES	ACP-10.1, ACP-10.3	5.2.12, 5.2.18	IX
X. INSPECTION	ACP-11.1, QUA-002, 003, 004, 005, 006, 008, 009, 010, 011	5.2.17	X
XI. TEST CONTROL	ACP-12.1	5.2.19	XI
XII. CONTROL OF MEASURING AND TEST EQUIPMENT	ACP-13.1	5.2.16	XII
XIII. HANDLING, STORAGE, & SHIPPING	ACP-14.0, ACP-30.1, IQI-2	5.2.13.4	XIII
XIV. INSPECTION, TEST AND OPERATING STATUS	ACP-2.3, ACP-11.1, ACP-12.1, ACP-15.1, ACP-15.2	5.2.6, 5.2.14	XIV
XV. NONCONFORMING MATERIALS, PARTS, OR COMPONENTS	ACP-16.0, QAI-7	5.2.14	XV
XVI. CORRECTIVE ACTION	ACP-17.1, 17.2, 17.3, 17.4	5.2.11	XVI
XVII. QUALITY ASSURANCE RECORDS	ACP-18.1	5.2.12	XVII
XVIII. AUDITS	QAI-5, QAI-6, ACP-19.0	4.5	XVIII

FIGURE 1




FIGURE 2

DAIRYLAND POWER COOPERATIVE  
MANAGEMENT ORGANIZATION

