

August 23, 2006

Mr. Ralph Butler, Director
Research Reactor Center
University of Missouri - Columbia
Research Park
Columbia, MO 65211

SUBJECT: NRC INSPECTION REPORT NO. 50-186/2006-203

Dear Mr. Butler:

On June 21-22, 2006, the US Nuclear Regulatory Commission (NRC) conducted a security inspection at your University of Missouri - Columbia Research Reactor facility. The inspection included a review of activities authorized for your facility. The enclosed report presents the results of that inspection.

The inspection examined activities conducted under your license as they relate to security and compliance with the Commission's rules and regulations, compliance with the conditions of your license, and implementation of certain compensatory measures. The inspector reviewed selected procedures and records, observed activities, and interviewed personnel. Based on the results of this inspection, no safety concerns or noncompliance with NRC requirements were identified. No response to this letter is required.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Website at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room). However, because of the security-related items contained in the enclosure, and in accordance with 10 CFR 2.390 (d), a copy of this letter's enclosure will not be available for public inspection.

Should you have any questions concerning this inspection, please contact Craig Bassett at 404-358-6515.

Sincerely,

/RA/

Johnny H. Eads, Branch Chief
Research and Test Reactors Branch B
Division of Policy and Rulemaking
Office of Nuclear Reactor Regulation

Docket No. 50-186
License No. R-103

Nonpublic Enclosure: NRC Inspection Report No. 50-186/2006-203

When detached from the enclosure, this letter is uncontrolled

University of Missouri-Columbia

Docket No. 50-186

cc:

University of Missouri
Associate Director
Research Reactor Facility
Columbia, MO 65201

A-95 Coordinator
Division of Planning
Office of Administration
P.O. Box 809, State Capitol Building
Jefferson City, MO 65101

Mr. Ron Kucera, Director
Intergovernmental Cooperation
and Special Projects
Missouri Department of Natural Resources
P.O. Box 176
Jefferson City, MO 65102

Mr. Tim Daniel
Homeland Security
Suite 760
P.O. Box 809
Jefferson City, MO 65102

Test, Research, and Training
Reactor Newsletter
University of Florida
202 Nuclear Sciences Center
Gainesville, FL 32611

August 23, 2006

Mr. Ralph Butler, Director
Research Reactor Center
University of Missouri - Columbia
Research Park
Columbia, MO 65211

SUBJECT: NRC INSPECTION REPORT NO. 50-186/2006-203

Dear Mr. Butler:

On June 21-22, 2006, the US Nuclear Regulatory Commission (NRC) conducted a security inspection at your University of Missouri - Columbia Research Reactor facility. The inspection included a review of activities authorized for your facility. The enclosed report presents the results of that inspection.

The inspection examined activities conducted under your license as they relate to security and compliance with the Commission's rules and regulations, compliance with the conditions of your license, and implementation of certain compensatory measures. The inspector reviewed selected procedures and records, observed activities, and interviewed personnel. Based on the results of this inspection, no safety concerns or noncompliance with NRC requirements were identified. No response to this letter is required.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be available electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of NRC's document system (ADAMS). ADAMS is accessible from the NRC Website at <http://www.nrc.gov/reading-rm/adams.html> (the Public Electronic Reading Room). However, because of the security-related items contained in the enclosure, and in accordance with 10 CFR 2.390 (d), a copy of this letter's enclosure will not be available for public inspection.

Should you have any questions concerning this inspection, please contact Craig Bassett at 404-358-6515.

Sincerely,
/RA/
Johnny H. Eads, Branch Chief
Research and Test Reactors Branch B
Division of Policy and Rulemaking
Office of Nuclear Reactor Regulation

Docket No. 50-186
License No. R-103
Nonpublic Enclosure: NRC Inspection Report No. 50-186/2006-203

DISTRIBUTION (w/o encl.):

PUBLIC PRT/R&TR r/f RidsNrrDprPrta RidsNrrDprPrtb
HNieh RidsOgcMailCenter BDavis (cover letter only)(O5-A4)
ADAMS Accession No.: ML062290450 TEMPLATE #: NRR-106
Package No.: ML062290434
Enclosure No.: ML062290452

OFFICE	PRTB:RI	PRTB:LA	PRTB:BC
NAME	CBassett:tls	EHylton	JEads
DATE	/ /2006	08 /23/2006	08 /23 /2006

OFFICIAL RECORD COPY