NRC FORM 591M PART 1 (10-2003) 10 CFR 2.201	U.S. NUCLEAR REGULATORY COMMISSION								
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION									
LICENSEE/LOCATION INSPECTED: J Core Drilling 43021 Braddock Road Centreville, Virginia 20120 REPORT Nos 2006-001		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415							
3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S								
030-36431	45-3	30846-01 July 26-27, 2006							
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: X									
Licensee's Statement of Corrective Actions for Item 4, above.									
I hereby state that, within 30 days, the actions descorrective actions is made in accordance with the right date when full compliance will be achieved). I under Title	requirements of 10 CFR 2.2	01 (corrective steps already n response to NRC will be re	taken, corrective steps which vequired, unless specifically req	will be taken, uested.					
	ILEU INAITIE	S	ignature	Date					
LICENSEE'S REPRESENTATIVE									
NRC INSPECTOR Craig Gord	don		/RA/	8/21/06					
NRC FORM 591M PART 1 (Rev. by RI 07/06) E:\Filenet\ML062340473.wpd									

SUNSI Review Completed By:	/RA/	Х	Public	Х	Non-Sensitive
----------------------------	------	---	--------	---	---------------