U.S. NUCLEAR REC	GULATORY COMMISSION	Date: 8/28/06
TELEPHONE CO	NVERSATION RECORD	Time:
Mail Control 139298 or Report No(s).	License No(s). 31-30666-01	Docket No(s). 030-35802
Name of Licensee:	Digirad Imaging Solutions, Inc. (DI	S)
Name of Participant(s):	see below	
Telephone No.	see below	
Subject: (NOTE: This will be used as the Documents Title in ADAMS)	RAI (8/28/06) concerning MC#139	298
Summary:	1433 East Michigan Avenue, Lansing, Michigan (Cardiology Group of Lansing) was listed on the DIS license as a base location. In a letter dated June 1, 2006, DIS requested that this location be removed from the license because RAM had not been used at this location in over a year. On 8/28/06 the Cardiology Group of Lansing was contacted to verify that all radioactive materials that were used at their facilities by DIS were removed. According to Katy Cox, Nuclear Medicine Technologist (517-482-2020), DIS last serviced their facility on 11/2/2005. At that time they removed all radioactive waste and performed a survey of the facility. No sealed sources were ever used at this site by DIS. On 11/7/2005 the Cardiology Group of Lansing was issued an NRC license. 2349 Mill Street, Aliquippa, Pennsylvania (offices of Sarvotham Shetty, M.D., 724-375-5401) was listed on the DIS license as a base location until it's removal from the license at the time the license renewal. On 8/28/06 Dr. Shetty's office was contacted to verify that no RAM was stored at that location by DIS. According to Donna Thomas, Office Manager, they are still clients of DIS. However, no RAM is delivered to the site when DIS is not there and no radioactive waste or sealed sources are stored at the site by DIS.	
Action Required: Remove the Lansing, Michigan site from DIS license.		
Document Availability:	X Publicly Available	Non-Publicly Available
X Non-Sensitive	Non-Sensitive Copyright S	Sensitive — Sensitive Copyright
Immediate Release	x Normal Release	Delay Release Date
Prepared & SUNSI Review Complete	ed By: TLWeidner	/ RA / Date: 8/28/06