



Sentara Williamsburg Regional Medical Center
100 Sentara Circle
Williamsburg, VA 23188

www.sentara.com

August 31, 2006

U.S. Nuclear Regulatory Commission, Region I Office
Division of NMSS, Attn: Materials Licensing
475 Allendale Road
King of Prussia, PA 19406

Br. 1

Re: license number 45-16209-02 03014703

To Whom It May Concern:

Please change the name of our facility for location and mailing purposes to Sentara Williamsburg Regional Medical Center at 100 Sentara Circle, Williamsburg, VA 23188. This represents a change in location and name only and ownership of this entity has not changed from Sentara.

We are requesting that our previous facility, Sentara Williamsburg Community Hospital at 301 Monticello Avenue, Williamsburg, be removed from our license and released for unrestricted use. The building, which has been vacated and checked for residual radiation and contamination, is pending transfer of ownership to the College of William and Mary.

No unsealed isotopes with half-lives over 120 days or leaking sealed sources were ever used in this hospital. See attached sealed source leak test results from July 2006.

Short-lived isotopes were used in treadmill areas and imaging rooms and ten half-lives have passed for those nuclides. Longer-lived nuclides were always prepared and administered in the hot lab, so only the hot lab was tested for removable contamination. Swipes checked in the CAPTUS well counter indicate no activity above background in the hot lab. Radiation level surveys of all nuclear medicine spaces indicated background readings only.

For more information, please do not hesitate to contact our Radiation Safety Officer, Sandy Wolff, at (757) 388-3030 or page her at (888) 341-5703.

Sincerely,

A handwritten signature in black ink, appearing to read 'R. Graves', written over a white background.

Robert Graves, FACHE
Vice President and Administrator

139354
NMSS/RGNI MATERIALS-002

Sentara Williamsburg Community Hospital
 301 Monticello Ave.
 Williamsburg, VA 23185
 NRC license 45-16209-02
 State license VA-062-01

Hot Lab Close-out Surveys and Wipes

Survey Meter

Eberline E-520 with pancake probe
 SN 1920
 Calibrated 4/7/06
 Background .02 mR/hr

Well Counter

Captus-500
 SN 000125
 Efficiency 33%
 Background 430 dpm

<u>Wipe #</u>	<u>Location Description</u>	<u>Survey Results</u>	<u>Wipes</u>	
			<u>net dpm</u>	<u>uCi</u>
1	Floor	0.02 mR/hr.	<0	0
2	Countertops	0.02 mR/hr.	0	0
3	Wall 1	0.02 mR/hr.	<0	0
4	Wall 2	0.02 mR/hr.	<0	0
5	Wall 3	0.02 mR/hr.	<0	0
6	Wall 4/Door	0.02 mR/hr.	<0	0
7	Sink/trap	0.02 mR/hr.	0	0

Surveys and wipes performed by Alek Colorado, CNMT, Nuclear Medicine Team Leader

Reviewed by Sandy Wolff, Radiation Safety Officer, 8-31-06

Sandy Wolff RSO

Sealed Sources Leak Test Report 07-01-2006 thru 07-31-2006

Date	Instrument	Chemical Name	Serial #	Cal. Date	Predicted Act.	Reading	Removable Act	In use	Tech
7/14/2006	2	Co-57	BM01101478	11-12-2004	2.10 mCi	★ 1,800.00 DPM	0.000811uCi	Y	SJW
	2	Co-57	65563	08-04-2005	103.57 uCi		0.000811uCi	Y	SJW
	2	Co-57	934-15-33	08-01-2002	0.12 mCi	18.00 DPM	0.000008uCi	Y	SJW
	2	Cs-137	3560759A-05	05-07-1979	112.93 uCi	8.00 DPM	0.000004uCi	Y	SJW
	2	Cs-137	A1764	11-01-1993	0.09 uCi		0.000004uCi	Y	SJW
	2	Co-57	BM0657-28-2	05-16-2005	1.80 mCi		0.000004uCi	Y	SJW

Instrument Details :

#	Instrument	Manufacturer	Next Cal Date	Serial No	Efficiency
2	CAPTUS-500	Capintec		000125	33.00%

This Report indicates that all above sealed sources have PASSED a Leak Test.
 Removed Activity for sources was below the 0.005 uCi NRC/STATE Trigger Limit

Technologist Signature : SJW RSO

★ Wipe re-counted next day, results zero (^{99m}Tc)
 SJW, RSO

This is to acknowledge the receipt of your letter/application dated

8/31/2006, and to inform you that the initial processing which includes an administrative review has been performed.

Amendment 45-16209-02 There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number** 139354.
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.