NRC FORM 591M PART (10-2003)	1		ι	U.S. NUCLEAR REGULATORY COMMISSION		
10 CFR 2.201 SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION						
 LICENSEE/LOCATION INSPECTED: Middlesex Hospital 28 Crescent Street Middletown, Connecticut 06457 			2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission			
		Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415				
REPORT Nos 2006001 3. DOCKET NUMBER(S) 4. L		4. LICENSE NUMBER(S	5. DATE(S) OF INSPECTION			
030-01242			4. LICENSE NOMBER(3) 06-00649-03		August 10, 2006	
LICENSEE:						
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows: Image: Imag						
Licensee's Statement of Corrective Actions for Item 4, above. I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken,						
date when full compliance Title	,	rstand that no further writte ited Name	en response to NRC will be rec	quired, unless specifically req anature	uested. Date	
LICENSEE'S REPRESENTATIVE					2010	
NRC INSPECTOR	Michelle S	immons	/	′RA/	08/16/06	
NRC FORM 591M PART 1 (Rev. by RI 07/06) E:\Filenet\ML062					ML062510201.wpd	
SUNSI Review Comp	leted By: /RA/		X P	ublic X Non-S	ensitive	