



FPL Energy.

Duane Arnold Energy Center

FPL Energy Duane Arnold, LLC
3277 DAEC Road
Palo, Iowa 52324

August 31, 2006

NG-06-0554
10 CFR 50 Appendix E Section V
10 CFR 72.44(f)

ATTN: Document Control Desk
Director, Spent Fuel Project Office
Office of Nuclear Material Safety & Safeguards
U. S. Nuclear Regulatory Commission
Washington, DC 20555-0001

Duane Arnold Energy Center
Docket 50-331
License No. DPR-49

Duane Arnold Energy Center Emergency Planning Department Procedure
Transmittal Acknowledgement Memos (TAMs) 167 and 197

Enclosed are the Duane Arnold Energy Center Emergency Planning Department Procedure Transmittal Acknowledgement Memos (TAMs) 167 and 197. TAM 167 contains revisions to Emergency Plan Implementing Procedures, and TAM-197 contains revisions to the Emergency Plan. These revisions have been reviewed pursuant to 10 CFR 50.54(q), as required, and it has been determined they do not decrease the effectiveness of the approved Emergency Plan.

This letter contains no new commitments and no revisions to existing commitments.

Please contact Paul Sullivan, Manager, Emergency Preparedness at (319) 851-7191, if you require further information.

A handwritten signature in black ink that reads "Gary D. Van Middlesworth".

Gary D. Van Middlesworth
Site Vice President, Duane Arnold Energy Center
FPL Energy Duane Arnold, LLC

AX45

Document Control Desk
Page 2 of 2

Enclosures: (2)

cc: Administrator, Region III, USNRC
Project Manager, DAEC, USNRC
Resident Inspector, DAEC, USNRC
Region III Incident Response Center (2 copies with 1 CD)

ENCLOSURE 1

DUANE ARNOLD ENERGY CENTER EMERGENCY PLANNING DEPARTMENT
PROCEDURE TRANSMITTAL ACKNOWLEDGEMENT MEMO TAM 167

26 pages follow

TAM-167 Summary of Changes

DAEC EPIP - EPIP Index

- 1) Changing the Index to mark EPIP forms annotated with an * identifying them as requiring a full 50.54q review completed on them upon revision. No actual change made to the EPIP Forms just protocol of requiring 50.54q review. Updating EPIP Index and making a global editorial change to all EPIP Forms by adding a note to the footer of each Form noting that the checklist does or doesn't require a 10CFR 50.54q review for changes.

DAEC EPIP 3.1 – Inplant Radiological Monitoring

- 1) Updating signature sheet to current standard format.
- 2) Changing reference #7 to ACP 1411.27 "Rules for Conduct of Work in Radiological Areas."
- 3) In the Note above 3.2(7), changing the reference from ACP 1411.22 to ACP 1411.27.

DAEC EPIP FORM CR-03 – Dose Projection & ARM Data Sheet

- 1) Revising Alarm set points to agree with actual set point as per ARPs.
- 2) Various Administrative changes.

DAEC EPIP FORM MIDAS-01 – MIDAS Operations

- 1) New procedure to provide better guidance for MIDAS operators.

DAEC EPIP FORM TSC-10 – Control Room Communicator Checklist

- 1) Revising cover sheet to include review/approval signatures.
- 2) On Page 2, Operation, Log pertinent Control Room information onto the ESB...
Selected Rad Monitor data, CHANGE: RR4448A/B to "using CR-03 Dose Projection & ARM Data Sheet" every 30-minutes or as conditions change.