

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

<b>1. LICENSEE/LOCATION INSPECTED:</b> Certified Testing Laboratories, Inc. 7801 Allentown Boulevard Harrisburg, Pennsylvania 17112  REPORT Nos 2006001	<b>2. NRC/REGIONAL OFFICE</b>  U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415
--	---

<b>3. DOCKET NUMBER(S)</b> 030-06219	<b>4. LICENSE NUMBER(S)</b> 37-09928-01	<b>5. DATE(S) OF INSPECTION</b> July 20, 2006
---	--	--

**LICENSEE:**  
 The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

- 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

License condition 16 requires, in part, that no sealed source shall be stored for a period of more than 3 years without being tested for leakage and/or contamination.

Contrary to the above, no leak test was performed on the Co-60 sealed source in the ICCSS exposure device, serial #586 from December 14, 1999 to July 19, 2006, a period greater than 3 years. The exposure device does not meet the current minimum standards for use as a radiography exposure device.

The licensee commits to leak testing the device within the week and disposing of the source prior to June 30, 2009. @

**Licensee's Statement of Corrective Actions for Item 4, above.**

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Jon H. Weik	<i>Jon H. Weik</i>	8/17/06
NRC INSPECTOR	Ronald G. Rolph	<i>Ronald G. Rolph</i>	8/17/2006