

Gamma Irradiator Service

Telephone 570-925-5681 Fax 570-925-5370

337 Distillery Hill Road
Benton, Pa. 17814

RECEIVED
REGION 1

br. 3

2006 SEP 14 PM 12:15

September 13, 2006

U.S. Nuclear regulatory Commission, Region 1


Request to amend NRC License 37-30850-01

03036438

This amendment is to add an 800 mCi Cs137 sealed source for the purpose of calibrating in house survey meters. Calibration procedures will follow the guidance of NUREG 1556 volume 7 appendix M, leak test will follow the guidance of NUREG 1556 Volume 18 Appendix O, calibration records will address the guidance of NUREG 1556 volume 7 Appendix M. The source will be stored and used at 337 Distillery Hill Road, Benton, PA 17814; the source will be transferred from North Carolina license number 034-0158-1 amendment 120. The source is a JL Shepherd Model 28-6 DOT 7A container S.N. 10252 capsule type is 3-M 4F65 special form UN 2974. The Bowman Gray School of Medicine is currently renewing their license and would like to have this removed. Upon amending my license I will notify "The Bowman Gray School of Medicine" so they can move forward with renewing their license. If any more information is required please call me at 570-924-5681. A timely response will be appreciated so that "The Bowman Gray School of Medicine" can amend their license.

Sincerely,

Doyle Terry Stout
Radiation Safety Officer

 9/13/06

139400

NMSS/RGNI MATERIALS-002

This is to acknowledge the receipt of your letter/application dated

9/13/2006, and to inform you that the initial processing which includes an administrative review has been performed.

Amendment 37-30850-01 There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned Mail Control Number 139400.
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.

NRC FORM 532 (R1)
(6-96)

Sincerely,
Licensing Assistance Team Leader