

UNITED STATES NUCLEAR REGULATORY COMMISSION REGION IV 611 RYAN PLAZA DRIVE, SUITE 400 ARLINGTON, TEXAS 76011-4005

October 17, 2006

Halliburton Energy Services, Inc. ATTN: Dwaine Brown Radiation Safety Officer 3000 N. Sam Houston Parkway, East Building M, Room M1F21 Houston, TX 77032-3219

SUBJECT: NRC INSPECTION REPORT 030-06392/2006-003 (FORM 591M Part 1)

Dear Mr. Brown:

This letter and the enclosed NRC Form 591M refer to the inspection conducted on August 9, 2006, at your facility located in Prudhoe Bay, Alaska. The inspection results were discussed with Mr. Mel Gabel, Facility Manager, at the conclusion of the inspection. A final exit briefing was conducted with you on October 17, 2006.

The inspection was an examination of activities conducted under your license as they relate to radiation safety, to compliance with the Commission's rules and regulations, and with the conditions of your license. Within these areas, the inspection consisted of selective examinations of procedures and representative records, interviews with personnel, independent measurements, and observation of activities in progress.

Within the scope of this inspection no violations or deviations were identified; therefore, no response to this letter or the enclosed NRC Form 591M is required.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter and its enclosure will be available electronically for public inspection in the NRC Public Document Room or from the NRC's document system (ADAMS). ADAMS is accessible from the NRC Web site at <u>http://www.nrc.gov/reading-rm/adams.html</u>.

Should you have any questions concerning this inspection or the enclosed report, please contact the undersigned at (817) 860-8143.

Sincerely,

/**RA**/

Randy R. Erickson Nuclear Materials Inspection Branch

Docket No.: 030-06392 License No.: 42-01068-07

Enclosure: As stated

cc w/enclosure: Texas Radiation Control Program Director Alaska Radiation Control Program Director Halliburton Energy Services, Inc.

bcc w/enclosure (via ADAMS e-mail distribution): LDWert CLCain VHCampbell JEWhitten RITS Coordinator NMIB RIV Materials Docket Files - 5th Floor

SUNSI Review Comp	leted:	RRE	ADAMS	Yes	<u>□</u> No	Initials: <u>RRE</u>
Publicly Available	□Non-	-Publicly Ava	ilable	Sensitive	Non-Sens	sitive

DOCUMENT NAME: s:\dnms\!nmib\!erio	ckson\60639203-591M.wpd	final	r:_dnms
RIV:DNMS:NMIB	C:NMIB		
RRErickson	VHCampbell		
/RA/	/RA/		
10/17/06	10/17/06		
OFFICIAL RECORD COPY	T=Telephone	E=E-mail	F=Fax

-2-

NRC FORM 591M PAR (10-2003)	T 1			U.S. NUCLEAR REGULATO	RY COMMISSION
10 CFR 2.201	SAFETY INSPI	ECTION REPORT AN			
 LICENSEE/LOCATION INSPECTED: Halliburton Energy Services, Inc. 3000 N. Sam Houston Parkway, East Building M, Room M1F21 Houston, TX 77032-3219 			2. NRC/REGIONAL OFFICE U.S. NRC Region IV 611 Ryan Plaza Drive, Suite 400 Arlington, Texas 76011-4005		
REPORT 3. DOCKET NUMBER(S)	2006-003	4. LICENSEE NUMBER(S)		5. DATE(S) OF INSF	PECTION
030-06392		42-01068-07		August 9, 2006	LOTION
LICENSEE:		12 01000 01		, laguer e, 2000	
The inspection was an ex Nuclear Regulatory Comr of procedures and repres	nission (NRC) rules and entative records, interviev e inspection findings, no v	regulations and the conditions of ws with personnel, and observat	of your license. The in	on safety and to compliance with spection consisted of selective e The inspection findings are as f	examinations
	and corrective action was			being cited because they were s E Enforcement Policy, NUREG-1	
	Non-Cited Violation(s) w	as/were discussed involving the	following requirement	(s) and Corrective Action(s):	
cited. This form		activities, as described below an TON, which may be subject to p		violation of NRC requirements ar	nd are being
	l iconsoo's	s Statement of Correctiv	e Actions for Iten	n 4 above	
corrective actions is made	30 days, the actions desc in accordance with the re will be achieved). I under	ribed by me to the inspector will equirements of 10 CFR 2.201 (o	l be taken to correct the corrective steps already	e violations identified. This stater v taken, corrective steps which w required, unless specifically required Signature	ill be taken,
LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR	Randy R. Ericks	son		/RA/	10/17/2006
			1		1