

NPA - PD - LR

From: Ram Subbaratnam
To: bford@entergy.com; Dellis1@entergy.com; fmogole@entergy.com
Date: 8/25/2006 10:49:34 AM
Subject: Final RAI on Section 2.4 - Scoping and screening Structures for the Pilgrim LRA

Folks:

Please find attached one set of formal RAIs on section 2.4 from the NRC staff on the Pilgrim LRA. I am sending you an advance copy so that Entergy can work on the lead in responding to the RAIs. As previously agreed upon, your formal response on docket will be due 30 days from the date of receipt of the RAIs in mail.

Thanking you.

Sincerely yours

Ram Subbaratnam
PM Pilgrim LRA
US NRC, (301) 415 1478

CC: Anissa Coates; Olivia Ricks

Mail Envelope Properties (44EF0DFE.1BD : 19 : 10294)

Subject: Final RAI on Section 2.4 - Scoping and screening Structures for the Pilgrim LRA
Creation Date 8/25/2006 10:49:34 AM
From: Ram Subbaratnam
Created By: RXS2@nrc.gov

Recipients	Action	Date & Time
entergy.com		
bford (<u>bford@entergy.com</u>)		
dellis1 (<u>Dellis1@entergy.com</u>)		
fmogole (<u>fmogole@entergy.com</u>)		

nrc.gov
 OWGWPO03.HQGWDO01
 ARC3 CC (Anissa Coates)

nrc.gov
 TWGWPO03.HQGWDO01
 OSR CC (Olivia Ricks)

Post Office	Delivered	Route
	Pending	entergy.com
OWGWPO03.HQGWDO01	Pending	nrc.gov
TWGWPO03.HQGWDO01	Pending	nrc.gov

Files	Size	Date & Time	
MESSAGE	916	8/25/2006 10:49:34 AM	
EGCBSection2.4RAIsFinal.wpd		38537	8/25/2006 10:45:12
AM			

Options

Auto Delete:	No
Expiration Date:	None
Notify Recipients:	Yes
Priority:	Standard
ReplyRequested:	No
Return Notification:	None

Concealed Subject:	No
Security:	Standard

To Be Delivered:
Status Tracking:

Immediate
Delivered & Opened

August 22, 2006

Mr. Michael Kansler
President
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601-1839

SUBJECT: REQUESTS FOR ADDITIONAL INFORMATION FOR THE REVIEW OF THE
PILGRIM NUCLEAR POWER STATION LICENSE RENEWAL APPLICATION
(TAC MC9669)

Dear Mr. Kansler:

By letter dated January 25, 2006, Entergy Nuclear Operations, Inc. submitted an application pursuant to 10 CFR Part 54, to renew the operating license for Pilgrim Nuclear Power Station for review by the U.S. Nuclear Regulatory Commission (NRC). The NRC staff is reviewing the information contained in the license renewal application and has identified, in the enclosure, areas where additional information is needed to complete the review. These requests for additional information address license Renewal Section 2.4, "Scoping and Screening Results: Structures."

These questions were discussed with a member of your staff, Bryan Ford, and a mutually agreeable date for this response is within 30 days from the date of this letter. If you have any questions, please contact me at 301-415-1478 or e-mail RXS2@nrc.gov.

Sincerely,

/RA/

Ram Subbaratnam, Project Manager
License Renewal Branch A
Division of License Renewal
Office of Nuclear Reactor Regulation

Docket No. 50-293

Enclosure:
Requests for Additional Information

cc w/encl: See next page

August 22, 2006

Mr. Michael Kansler
President
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601-1839

**SUBJECT: REQUESTS FOR ADDITIONAL INFORMATION FOR THE REVIEW OF THE
PILGRIM NUCLEAR POWER STATION LICENSE RENEWAL APPLICATION
(TAC MC9669)**

Dear Mr. Kansler:

By letter dated January 25, 2006, Entergy Nuclear Operations, Inc. submitted an application pursuant to 10 CFR Part 54, to renew the operating license for Pilgrim Nuclear Power Station for review by the U.S. Nuclear Regulatory Commission (NRC). The NRC staff is reviewing the information contained in the license renewal application and has identified, in the enclosure, areas where additional information is needed to complete the review. These requests for additional information address license Renewal Section 2.4, "Scoping and Screening Results: Structures."

These questions were discussed with a member of your staff, Bryan Ford, and a mutually agreeable date for this response is within 30 days from the date of this letter. If you have any questions, please contact me at 301-415-1478 or e-mail RXS2@nrc.gov.

Sincerely,

/RA/

Ram Subbaratnam, Project Manager
License Renewal Branch A
Division of License Renewal
Office of Nuclear Reactor Regulation

Docket No. 50-293

Enclosure:
Requests for Additional Information

cc w/encl: See next page

ADAMS Accession No.: ML062350440

C:\temp\EGCBSection2.4RAIsFinal.wpd

OFFICE	PM:RLRA:DLR	LA:RLRA:DLR	BC:REBB:DLR	OGC
NAME	RSubbaratnam	IKing	LLund (Rauluck for)	MZobler
DATE	8/15/06	8/14/06	8/18/06	8/22/06

OFFICIAL RECORD COPY

Letter to Michael Kansler from Ram Subbaratnam dated: August 22, 2006

SUBJECT: REQUESTS FOR ADDITIONAL INFORMATION FOR THE REVIEW OF THE
PILGRIM NUCLEAR POWER STATION LICENSE RENEWAL APPLICATION
(TAC MC9669)

HARD COPY

DLR R/F

E-MAIL:

JFair

RWeisman

AMurphy

RPettis

GGalletti

DShum

GBagchi

SSmith (srs3)

SDuraiswamy

YL (Renee) Li

RidsNrrDir

RidsNrrDirRlra

RidsNrrDirRlrb

RidsNrrDe

RidsNrrDci

RidsNrrEemb

RidsNrrDeEeeb

RidsNrrDeEqva

RidsNrrDss

RidsNrrDnrl

RidsOgcMailCenter

RidsNrrAdes

DLR Staff

RSubbaratnam

SHoffman

SUttal

JShea

AWilliamson

DJeng

RKaras

Sai Wah NG

GWilson

CAnderson, Region 1

WRaymond, Region 1

NSheehan, Region 1

Pilgrim Nuclear Power Station

cc:

Regional Administrator, Region I
U. S. Nuclear Regulatory Commission
475 Allendale Road
King of Prussia, PA 19406-1415

Senior Resident Inspector
U. S. Nuclear Regulatory Commission
Pilgrim Nuclear Power Station
Post Office Box 867
Plymouth, MA 02360

Chairman, Board of Selectmen
11 Lincoln Street
Plymouth, MA 02360

Chairman
Nuclear Matters Committee
Town Hall
11 Lincoln Street
Plymouth, MA 02360

Chairman, Duxbury Board of Selectmen
Town Hall
878 Tremont Street
Duxbury, MA 02332

Office of the Commissioner
Massachusetts Department of
Environmental Protection
One Winter Street
Boston, MA 02108

Office of the Attorney General
One Ashburton Place
20th Floor
Boston, MA 02108

Director, Radiation Control Program
Commonwealth of Massachusetts
Executive Offices of Health and
Human Services
174 Portland Street
Boston, MA 02114

Secretary of Public Safety
Executive Office of Public Safety
One Ashburton Place
Boston, MA 02108

Director, Massachusetts Emergency
Management Agency
Attn: James Muckerheide
400 Worcester Road
Framingham, MA 01702-5399

Mr. William D. Meinert
Nuclear Engineer
Massachusetts Municipal Wholesale
Electric Company
P.O. Box 426
Ludlow, MA 01056-0426

Mr. Michael A. Balduzzi
Site Vice President
Entergy Nuclear Operations, Inc.
Pilgrim Nuclear Power Station
600 Rocky Hill Road
Plymouth, MA 02360-5508

Mr. Stephen J. Bethay
Director, Nuclear Safety Assurance
Entergy Nuclear Operations, Inc.
Pilgrim Nuclear Power Station
600 Rocky Hill Road
Plymouth, MA 02360-5508

Mr. Bryan S. Ford
Manager, Licensing
Entergy Nuclear Operations, Inc.
Pilgrim Nuclear Power Station
600 Rocky Hill Road
Plymouth, MA 02360-5508

Mr. Gary J. Taylor
Chief Executive Officer
Entergy Operations
1340 Echelon Parkway
Jackson, MS 39213

cc:

Mr. John T. Herron
Sr. VP and Chief Operating Officer
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Mr. Oscar Limpias
Vice President, Engineering
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Mr. Christopher Schwarz
Vice President, Operations Support
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Mr. John F. McCann
Director, Nuclear Safety Assurance
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Ms. Charlene D. Faison
Manager, Licensing
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Mr. Michael D. Lyster
5931 Barclay Lane
Naples, FL 34110-7306

Mr. Michael J. Colomb
Director of Oversight
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Ms. Stacey Lousteau
Treasury Department
Entergy Services, Inc.
639 Loyola Avenue
New Orleans, LA 70113

Mr. James Sniezek
5486 Nithsdale Drive
Salisbury, MD 21801

Mr. Travis C. McCullough
Assistant General Counsel
Entergy Nuclear Operations, Inc.
440 Hamilton Avenue
White Plains, NY 10601

Mr. James Ross
Nuclear Energy Institute
1776 I Street, NW, Suite 400
Washington, DC 20006-3708

Plymouth Public Library
Attn: Dinah O'Brien
132 South Street
Plymouth, MA 02360

Duxbury Free Library
ATTN: Ms. Elaine Winquist
77 Alden Street
Duxbury, MA 02332

Kingston Public Library
ATTN: Reference Librarian
6 Green Street
Kingston, MA 02364

Ms. Mary Lampert
Duxbury Nuclear Advisory, Chair
Pilgrim watch, Director
148 Washington Street
Duxbury 02332

REQUEST FOR ADDITIONAL INFORMATION
PILGRIM LICENSE RENEWAL APPLICATION (LRA)
SECTION 2.4 SCOPING AND SCREENING RESULTS: STRUCTURES

Section 2.4.1 Primary Containment

RAI 2.4.1-1

Table 2.4-1, Primary Containment of the license renewal application (LRA) does not include drywell head closure bolts, backing plates, spring seals, and removable guard rings. These components have the intended function of pressure boundary and support for criterion (a)(1) equipment. The staff requests the applicant provide justification for not including them in the scope of license renewal.

RAI 2.4.1-2

Neither Table 2.4-1, Primary Containment, nor Table 2.4-2, Reactor Building, of the LRA incorporates refueling cavity seal components within the scope of license renewal. The proposed license renewal interim staff guidance LR-ISG-2006-01, "Plant Specific Aging Management Program for Inaccessible Areas of Boiling Water Reactor Mark 1 Steel Containment Drywell Shell," which was published in the Federal Register on May 9, 2006, stated that the most likely cause of corrosion of the drywell shell in the sand-pocket areas (near the bottom of the drywell), and in the spherical portion of the drywell at higher elevations, was the water in the gap between the drywell and the concrete shield, and the source of the water was noted as leakage through the seal between the drywell and the refueling cavity. Therefore, the staff requests the applicant include all the refueling cavity seal components within the scope of license renewal and provide a drawing that depicts the refueling cavity seal components.

RAI 2.4.1-3

Table 2.4-2, Reactor Building, of the LRA lists the biological shield wall concrete as a component within the scope of license renewal. Clarify if the Pilgrim Nuclear Power Station (Pilgrim) plant needs a cooling system to maintain the temperature of the biological shield wall concrete within its design limit temperatures. If yes, confirm that the cooling system is included within the scope of license renewal and list the system in Table 2.4-2.

RAI 2.4.1-4

Table 2.4-1, Primary Containment, of the LRA lists "Floor slabs, walls (EQ Zone 1.30, Drywell El. 9'-2")." It is unclear to the staff if the above referenced slab is the same as the one located at the elevation of the moisture barrier which serves as the interface between the drywell floor concrete slab and the drywell shell. Provide a drawing to depict the "Floor slabs, walls (EQ Zone 1.30, Drywell El. 9'-2")," and indicate whether all floor slabs and walls inside the primary containment are within the scope of license renewal.

ENCLOSURE

RAI 2.4.1-5

Table 2.4-1, Primary Containment, of the LRA does not include the reinforced concrete shield plugs that provide shielding over the top of the drywell. The staff requests the applicant provide justification for not including them in the scope of license renewal. Exclusion of the reinforced concrete shield plugs from the scope of license renewal may lead to long-term unmanaged degradation of the plugs (e.g., full sectional concrete cracking, rebar corrosion, loss of bond, partial spalling or cracking of concrete due to handling, loss of load carrying capacity of plug attachments, etc.) with a seismic II/I implication potentially affecting the structural integrity of the drywell head.

RAI 2.4.1-6

Table 2.4-1, Primary Containment, of the LRA only lists the reactor vessel and drywell bellows. Confirm that items such as backing plates, spring seals, and removable guard rings are within the scope of license renewal and list the items in Table 2.4-1.

Section 2.4.3 Intake Structure

RAI 2.4.3-1

Table 2.4-3, Intake Structure, of the LRA does not include intake structure components specific to Pilgrim, such as sluice gates, trash racks, traveling screens, cranes and water proofing membranes, etc. within the scope of license renewal. As applicable, the staff requests the applicant provide justification for not including them in the scope of license renewal.

Section 2.4.4 Process Facilities

RAI 2.4.4-1

Section 2.4.4, Process Facilities, of the LRA under Main Stack and Filter Building states that "The main stack is a safety-related and seismic Class I structure but is not designed to withstand tornado loadings since it is located sufficiently far from other seismic Class I structures to preclude interaction." The staff needs additional information regarding the potential interaction between some seismic Class II structure, system, and components (SSCs) and the tornado-induced failure of the main stack. Specifically, the licensee is requested to confirm that appropriate measures have been taken to preclude potential interactions between the main stack and some nearby seismic Class II SSCs whose failure might have adverse effects on seismic Class I SSCs.

Section 2.4.5 Yard Structures

RAI 2.4.5-1

Table 2.4-5, Yard Structures, of the LRA does not include, the plant system portion of switchyard circuit breakers, transformers, transmission towers, and transmission tower foundations. As part of the list to comply with interim staff guidance(ML020920464) concerning scoping of offsite power systems necessary to support the Station Blackout Rule (10 CFR 50.63), the staff requests the applicant include these components in the scope of license

renewal. The ADAMS Public Electronic Reading Room is accessible at <http://www.nrc.gov/reading-rm/adams.html> on the NRC web site. Persons who do not have access to ADAMS, should contact the NRC's Public Document Room reference staff at 1-800-397-4209, or 301-415-4727, or by e-mail at pdr@nrc.gov.

Section 2.4.6 Bulk Commodities

RAI 2.4.6-1

Table 2.4-6, Bulk Commodities, of the LRA provides a list of bulk commodities for Pilgrim. The location of each commodity is unclear to the staff. The staff requests the applicant describe all commodities on the list as well as provide a comprehensive listing of components and locations for each commodity.

RAI 2.4.6-2

Table 2.4-6, Bulk Commodities, of the LRA lists "Insulation" with its intended functions. It is unclear to the staff why "Support for Criterion (a)(1) equipment" is not part of the intended functions when Table 2.0-1 defines the intended function of insulation as "provide insulating characteristics to reduce heat transfer," which is meant to apply to safety related and non-safety related components. The staff requests the applicant provide additional information on insulation and a list of in-scope components that have insulation included with their intended functions.

RAI 2.4.6-3

Table 2.4.6 lists steel "Flood curbs" as a component with intended functions for flood barrier and shelter or protection, and another component concrete "Flood curbs" with an intended function for flood barrier. The staff requests the applicant provide clarifications for the two different components by listing all structural members (elements) under each component.