



UNITED STATES
NUCLEAR REGULATORY COMMISSION
WASHINGTON, D.C. 20555-0001
~~SAFEGUARDS INFORMATION~~


Mr. Michael Balduzzi
Site Vice President
Pilgrim Nuclear Power Station
600 Rocky Hill Road
Plymouth, MA 02360

SUBJECT: PILGRIM ~~FORCE-ON-FORCE~~ INSPECTION REPORT 05000293/2005201

Dear Mr. Balduzzi:

On July 29, 2005, the US Nuclear Regulatory Commission (NRC) completed a ~~force-on-force~~ team inspection at the Pilgrim Nuclear Power Station. The enclosed inspection report documents the inspection results, which were discussed on July 29, 2005, with you and other members of your staff.

The inspection examined activities under your license as they relate to physical security and compliance with the Commission's rules and regulations and with the conditions of your license. The inspectors reviewed selected procedures and records, observed activities, and interviewed personnel.



ex 2

WARNING: Violation of Section 147 of the Atomic Energy Act, "Safeguards Information" is subject to Civil and Criminal Penalties

Safeguards Information determination made by:
Name Title Ralph W. [Signature] Operations Director
Organization DNS/NSR
Basis 10 CFR 73.2
Signature [Signature] Date 7/22/05

Enclosure contains Safeguards Information. Upon removal, this letter is exempt from public disclosure in accordance with 10 CFR 2.390.

Information in this record was deleted in accordance with the Freedom of Information Act, exemptions 2, 3, 1
FOIA- 2006-1597
~~SAFEGUARDS INFORMATION~~

F-4


M. Balduzzi

-2-

The material enclosed herewith contains Safeguards Information as defined by 10 CFR 73.21 and its disclosure to unauthorized individuals is prohibited by Section 147 of the Atomic Energy Act of 1954, as amended. In addition, this letter contains sensitive information as defined in 10 CFR 2.390. As such, neither this letter nor the enclosure will be made available in hard copy or electronically for public inspection in the NRC Public Document Room or from the Publicly Available Records (PARS) component of the Agency-Wide Documents Access and Management System (ADAMS).

Should you have any questions concerning this letter, please contact Mr. Ronald J. Albert of my staff at (301) 415-6692.

Sincerely,



Ralph Way, Deputy Director
Nuclear Security Operations
Division of Nuclear Security
Office of Nuclear Security and Incident Response

Docket No.: 50-293
License No.: DPR-35

Enclosure: NRC Inspection Report No. 05000293/2005201

cc w/ enclosure:

Edward A. Flynn
Secretary, Executive Office of Public Safety
1 Ashburton Room 2133
Boston, MA 02133

Christine McCombs
Massachusetts Emergency Management Agency
400 Worcester Road
Framingham, MA 01701

M. Balduzzi

-3-

cc w/o encl:

John M. Fulton
General Counsel
Pilgrim Nuclear Power Station
600 Rocky Hill Road
Plymouth, MA 02360

Chris Kelly
Security Director
Entergy Nuclear Operations, Inc.
1340 Echelon Parkway, 5th Floor
Jackson, MS 39213

Bryan Ford
Licensing Manager
Pilgrim Nuclear Power Station
600 Rocky Hill Road
Plymouth, MA 02360

Fred Marcussen
Security Manager
Pilgrim Nuclear Power Station
600 Rocky Hill Road
Plymouth, MA 02360

U.S. NUCLEAR REGULATORY COMMISSION
OFFICE OF NUCLEAR SECURITY AND INCIDENT RESPONSE (NSIR)

Report Nos.: 05000293/2005201
Licensee: Entergy Nuclear Generation Company
Facility: Pilgrim Nuclear Power Station
Location: Plymouth, MA
Dates: June 28 - 30, 2005 and
July 26 - 29, 2005
Inspectors: R. John Vanden Berghe, Team Leader, NSIR
David R. Bradfield, Security Specialist, NSIR
Carl Grigsby, Security Specialist, NSIR
Vincent Klco, Reactor Engineer, NSIR
Greg Smith, Physical Security Inspector, R-I
Joseph Anderson, Emergency Preparedness Specialist, NSIR
NRC Contractors (2)

CAF Members:

EA 2



Approved by: Ronald J. Albert, Chief
Security Performance Evaluation Section
Division of Nuclear Security, NSIR

Enclosure

~~SAFEGUARDS INFORMATION~~

SUMMARY OF FINDINGS

IR 05000293/2005201; 06/28-30/2005 and 07/26-29/2005; Pilgrim Nuclear Power Station; Contingency Response, Force-on-Force Testing, Inspection Procedure 71130.03

The report covered an announced force-on-force inspection by a team of inspectors from the Office of Nuclear Security and Incident Response (NSIR) and Region I. The inspectors were assisted by NRC contractors. [REDACTED]

EH

843

SAFEGUARDS INFORMATION

Report Details

3. SAFEGUARDS

Cornerstone: Physical Protection (PP)

3PP3 Contingency Response - Force-on-Force Testing

3.1 Entrance Briefing

a. Scope

The inspectors met with licensee management and conducted an Entrance Briefing. The team leader conducted appropriate introductions; provided the inspection number, and identified the applicable inspection procedure and the duration of the inspection; presented key areas to be inspected and discussed [REDACTED]

Ext 2


[REDACTED] identified the number of responders to be used for exercises; explained the trusted agent process; explained that exercises would be conducted with the full knowledge of a licensee manager; explained the significance determination process and enforcement; established a licensee point of contact and confirmed a schedule of inspections activities; and established a date and time for the Exit Meeting.

b. Summary

On June 28, 2005, the team leader presented the inspection scope and planned inspection activities to Mr. Robert Smith, Engineering Director and Acting Site Vice President, and members of the licensee staff.

3.2 Management Overview of Protective Strategy and Associated Policies

a.



3