

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED: Advanced Mobile Services 911 E. Nine Mile Road Ferndale, MI 48220  REPORT NUMBER(S) 2006/001		2. NRC/REGIONAL OFFICE REGION III US NUCLEAR REGULATORY COMMISSION 801 WARRENVILLE ROAD LISLE IL 60532-4351	
3. DOCKET NUMBER(S) 030-36178	4. LICENSE NUMBER(S) 21-32436-01	5. DATE(S) OF INSPECTION 11/30/2006	

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.


\_\_\_\_\_ non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

**Statement of Corrective Actions**

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE			
NRC INSPECTOR	Sarah Bakhsh		11/30/2006

**Docket File Information**  
**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED: <b>Advanced Mobile Services</b> REPORT NUMBER(S) 2006/001		2. NRC/REGIONAL OFFICE <b>REGION III</b>			
3. DOCKET NUMBER(S) <b>030-36178</b>		4. LICENSE NUMBER(S) <b>21-32436-01</b>		5. DATE(S) OF INSPECTION <b>11/30/2006</b>	
6. INSPECTION PROCEDURES USED <b>IP 87130</b>		7. INSPECTION FOCUS AREAS <b>03.01-03.07</b>			

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S) <b>02220</b>	2. PRIORITY <b>3</b>	3. LICENSEE CONTACT <b>Rodolfo Farhy, MD</b>	4. TELEPHONE NUMBER <b>313-581-2600</b>
------------------------------------	-------------------------	-------------------------------------------------	--------------------------------------------

- Main Office Inspection      Next Inspection Date: 11/2009  
 Field Office Inspection    Mobile Site(clinic at 23600 Harper Ave)  
 Temporary Job Site Inspection \_\_\_\_\_

**PROGRAM SCOPE**

The licensee was a medical clinic with mobile nuclear medicine service located in Ferndale, Michigan. The licensee was authorized to conduct licensed activities under 10 CFR 35.100 and 35.200. The licensee employed two nuclear medicine technologists (NMT). The licensee had 3 mobile vans which they took to clients' offices, with which they had agreements, in southeast and lower Michigan. The NMTs performed approximately 35 diagnostic procedures weekly (per van) at the clients' facilities. The procedures were performed using technetium-99m which was delivered to the main office by a local pharmacy. All waste was either held for decay-in-storage or returned to the pharmacy.

The inspector completed TI 2800/039 for this facility and inspected the licensee's NMTs' use of material at one of the licensee's client facilities. The licensee did not perform any procedures at the main office at the time of this inspection.

**PERFORMANCE OBSERVATIONS**

During the inspection, the inspector reviewed select records (dose records for NMT present at the South Linden facility during the inspection were not available) and observed: (1) administration of the radioactive material by the technologist at the client's facility; (2) adequate security of the licensed material; (3) adequate posting of areas; (4) package receipt and return surveys; (5) responses to emergency scenarios; (6) survey meter use and calibration; (7) daily and weekly contamination surveys; and (8) dose calibrator constancy checks.

No violations of NRC requirements were identified.