

Michael P. Gallagher, PE
Vice President
License Renewal Projects

Telephone 610.765.5958
www.exeloncorp.com
michaelp.gallagher@exeloncorp.com

An Exelon Company

AmerGen
200 Exelon Way
KSA/2-E
Kennett Square, PA 19348

10 CFR 50
10 CFR 51
10 CFR 54

2130-06-20441
December 15, 2006

U. S. Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555

Oyster Creek Generating Station
Facility Operating License No. DPR-16
NRC Docket No. 50-219

Subject: Editorial Correction to AmerGen's Letter 2130-06-20426 "Information from October 2006 Refueling Outage Supplementing AmerGen Energy Company, LLC (AmerGen) Application for a Renewed Operating License for Oyster Creek Generating Station (TAC No. MC7624)," dated December 3, 2006

References: 1. AmerGen's Letter 2130-06-20426, "Information from October 2006 Refueling Outage Supplementing AmerGen Energy Company, LLC (AmerGen) Application for a Renewed Operating License for Oyster Creek Generating Station (TAC No. MC7624)," dated December 3, 2006

2. AmerGen's Letter 2130-06-20414, "AmerGen Responses to Open Items Associated with the NRC Draft Safety Evaluation for the Oyster Creek Generating Station Application for License Renewal (TAC No. MC7624)," dated October 20, 2006

3. AmerGen's Letter 2130-06-20358, "Additional Information Concerning FSAR Supplement Supporting the Oyster Creek Generating Station License Renewal Application (TAC No. MC7624)," dated July 7, 2006

In Reference 1, AmerGen submitted information summarizing inspection results and new commitments stemming from the October 2006 Oyster Creek refueling outage, to support the NRC staff's review of AmerGen's associated license renewal application. In its presentation of the new commitments (Table A.5, License Renewal Commitment List, sub-items 14 through 17 of IWE Program commitment #27), AmerGen inadvertently included outdated information in its description of existing IWE Program commitment # 27, sub-items 10 and 11.

Reference 2 correctly describes IWE Program commitment # 27, sub-items 10 and 11. This was clarified verbally with the NRC staff on December 13, 2006.

Note that this correction applies to three sections of Reference 1, as follows:

- 1) Section A.1.27, ASME Section XI, Subsection IWE, Aging Management Program Description (page 38 of 74),
- 2) Table A.5, License Renewal Commitment List (pages 45 and 46 of 74), and
- 3) Section B.1.27, ASME Section XI, Subsection IWE, Aging Management Program Description (page 52 of 74).

A114
A047

Similarly, the ASME Section XI, Subsection IWE Program descriptions (Appendix A, Section A.1.27 and Appendix B, Section B.1.27) submitted in Reference 1 also contained outdated information in its description of IWE program elements 12 and 13. Reference 3 correctly describes IWE program elements 12 and 13. The commitment descriptions as described in the updated A.5 list of Reference 1 were correct as submitted.


Neither of these corrections affects the post-2006 refueling outage information that was provided in Reference 1. Both serve to make Reference 1 consistent with information submitted previously in References 2 and 3.

If you have any questions, please contact Fred Polaski, Manager License Renewal, at 610-765-5935.

I declare under penalty of perjury that the foregoing is true and correct.

Respectfully,

Executed on 12-15-06



Michael P. Gallagher
Vice President, License Renewal
AmerGen Energy Company, LLC

cc: Regional Administrator, USNRC Region I
USNRC Project Manager, NRR - License Renewal, Safety
USNRC Project Manager, NRR - License Renewal, Environmental
USNRC Project Manager, NRR - Project Manager, OCGS
USNRC Senior Resident Inspector, OCGS
Bureau of Nuclear Engineering, NJDEP
File No. 05040