

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

1. LICENSEE U. S. Inspection Services REPORT NUMBER(S) 2006-003		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 030-35059	4. LICENSE NUMBER(S) 34-06943-02	5. DATE(S) OF INSPECTION November 30, 2006	
6. INSPECTION PROCEDURES USED 87126	7. INSPECTION FOCUS AREAS 03.01 - 03.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03320	2. PRIORITY 1	3. LICENSEE CONTACT Mark Rinke	4. TELEPHONE NUMBER 248/651-0770
-----------------------------	------------------	-----------------------------------	-------------------------------------

Main Office Inspection Next Inspection Date: 11/06

Field Office _____

Temporary Job Site _____

PROGRAM SCOPE

The licensee is a radiographer located in Rochester, Michigan with authorization to use material at temporary job sites where the NRC maintains jurisdiction. This licensee has six full time radiographers and is in possession of two 880 exposure devices.

Performance Observations

At the time of the inspection, licensee was not performing radiography using a gamma source. Therefore no temporary job site was observed. The inspector reviewed the paperwork associated with the use of the radiographic devices and interviewed personnel that performed radiography. All personnel appeared to possess an adequate level of knowledge of radiation protection.

Independent surveys around the storage facility yielded minimal results. Although licensee personnel are badged, readings for the past year were low and did not exceed 500 mRem on average.

No violations of requirements were noted.



