

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

1. LICENSEE Testmaster Inspection REPORT NUMBER(S) 2006-002		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 030-35090	4. LICENSE NUMBER(S) 34-24872-02	5. DATE(S) OF INSPECTION November 28, 2006	
6. INSPECTION PROCEDURES USED 87126	7. INSPECTION FOCUS AREAS 03.01 - 03.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03320	2. PRIORITY 1	3. LICENSEE CONTACT Wendell Carr	4. TELEPHONE NUMBER 419/666-7526
-----------------------------	------------------	-------------------------------------	-------------------------------------

Main Office Inspection Next Inspection Date: 11/07

Field Office _____

Temporary Job Site _____

PROGRAM SCOPE

The licensee is an industrial radiographer located in Perrysburg, Ohio with authorization to use material at temporary job sites where the NRC maintains jurisdiction. This licensee has four full time radiographers and is in possession of twelve 660 exposure devices containing sources up to 100 curies each.

Performance Observations

At the time of the inspection, licensee was not performing radiography due to a general lack of work. The inspection of facilities was limited in scope since licensee is located in an Agreement State. The inspector reviewed the paperwork associated with the use of the radiographic devices and interviewed personnel that performed radiography. All personnel appeared to possess an adequate level of knowledge of radiation protection.

Independent surveys around the storage facility yielded minimal results. Although licensee personnel are badged, readings for the past year were generally low and ranged to 1400 mRem/yr.

No violations of requirements were noted.

ML063530345

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED: Testmaster Inspection Co P.O. Box 31 Perrysburg, Oh 43552 REPORT 2006 001	2. NRC/REGIONAL OFFICE US Nuclear Regulatory Comm Reg 111 2443 Warranville Rd Suite 210 Hiale, FL 33012	
3. DOCKET NUMBER(S) 030-35090	4. LICENSEE NUMBER(S) 34-24872-02	5. DATE(S) OF INSPECTION Nov 28, 2006

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

1. Based on the inspection findings, no violations were identified.

2. Previous violation(s) closed.

3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	G. Parker		11/28/06

RP