

APPENDIX A

NOTICE OF VIOLATION

Department of the Army
U. S. Army Electronics Research
Development Command, DELSD-SF
Ft. Monmouth, New Jersey 07703
License Nos. 29-01022-07
29-01022-10

Docket Nos. 30-6989
30-9718

Based on the results of an NRC inspection conducted on October 20 and November 1, 1978, it appears that certain of your activities were not conducted in full compliance with the conditions of your NRC licenses as indicated below:

- A. Condition 16 of License No. 29-01022-07 requires that licensed material be possessed and used in accordance with the statements, representations, and procedures contained in certain referenced applications.

Your application dated May 5, 1976, contains Operating Procedures for the Underground Vault Cobalt-60 Irradiation Facility. Item 15.a of these procedures requires that when the lead door to the exposure room is opened, the action of the interlock will cause the source to be lowered into the source container.

Contrary to this requirement, on October 20, 1978, the source was not lowered into the source container when the lead door to the exposure room was opened.

This is an infraction.

- B. Condition 15 of License No. 29-01022-10 requires that licensed material be possessed and used in accordance with the statements, representations, and procedures contained in your application received June 12, 1978. Section 2.c of Enclosure 7 to this application (last paragraph, page 7-2) requires that if the level of the water in your pool irradiator tank drops more than 6 inches, an audible alarm will sound.

BB/17

OFFICE ▶						
SURNAME ▶						
DATE ▶						

Contrary to this requirement, on October 20, 1978, the system which would produce an audible alarm if the level of the water in the pool dropped, was inoperable.

This is an infraction.

OFFICE ▶					
SURNAME ▶					
DATE ▶					