



PPG High Performance Coatings

856 Echo Lake Road

P. O. Box 460

Watertown, CT 06795

Tel: 860-274-6701

Fax: 860-274-5857

October 10, 2006

Description of Pictures TXU Comanche Peak SES Report #06-0413

Picture Number	Description
DSCN3163.JPG	Paint chips as received showing topcoat
DSCN3164.JPG	Paint chips as received showing IOZ primer
DSCN3168.JPG	Paint chips in lower rack ready for loading onto bottom holder.
DSCN3169.JPG	Paint chips racked, looking at the top holder, prior to testing.
DSCN3172.JPG	Paint chips racked and loaded into autoclave, prior to testing.
DSCN3196.JPG	Post DBA Testing, looking at the top rack.
DSCN3202.JPG	Post DBA Testing, looking at the lower rack.
DSCN3209.JPG	Left filters used for testing, right filter unused.
DSCN3214.JPG	Looking into bottom of autoclave after completion of test. Note debris in bottom of autoclave.
DSCN3261.JPG	Smaller debris removed from lower rack, separated from larger chips.
DSCN3262.JPG	Smaller debris removed from upper rack, separated from larger chips.
DSCN3264.JPG	Paint chips removed from upper rack ready for weighing
DSCN3265.JPG	Paint chips removed from lower rack ready for weighing
DSCN3266.JPG	Paint chip samples being weighed on analytical balance.
DSCN3270.JPG	Sample of paint chip removed from upper rack. Note curling effect associated with DBA Testing.
DSCN3588.JPG	Paint chip debris removed from bottom of autoclave.