



Superior Well Services, Ltd.
1380 RT 286 East Suite #121
Indiana, PA 15701
Telephone 724-465-8904

February 5, 2007

United States Nuclear Regulatory Commission
Nuclear Materials Safety Branch
475 Allendale Road
King of Prussia, PA 19406
Att: Licensing Assistance Team

N 1583

03034542

Re: Amendment to USNRC License #37-30412-01

Dear Licensing Assistance Team,

Superior Well Services, Ltd. requests an amendment to USNRC Specific License Number 37-30412-01. The requested changes include:

- Removal of the authorization for possession and use of the Cesium-137 sealed source and device identified in License Condition 6.D and 9.D.
- Addition of QSA Global Model CDC.CYN (MA-1059-S-191-S)
(N = source number)

The sources and devices requested for removal from the specific license are authorized for distribution and possession under general license regulations as referenced in Sealed Source and Device Registry Number (TX-0634D105B). The Superior Well Services, Ltd. devices have been confirmed to contain the general license label. Leak tests have been conducted on a routine basis with no leakage identified.

No additional revisions are requested at this time. Superior Well Services, Ltd. shall continue to manage the Radiation Safety Program as described in previous correspondence. Licensed material shall be properly secured when not under direct surveillance of logging supervisors or assistants.

If there are any questions, please contact Daniel Coffee at 330-705-8301.

Best regards,

David E. Wallace
CEO
Superior Well Services, Ltd.

RECEIVED
REGION 1
2007 FEB 13 AM 10:36

140091

NMSS/RGN MATERIALS-002

This is to acknowledge the receipt of your letter/application dated

2/5/2007, and to inform you that the initial processing which includes an administrative review has been performed.

AMCMB. 37-30412-01
There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned **Mail Control Number** 140081.
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.