

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION



1. LICENSEE DBI, Inc. REPORT NUMBER(S) 2007-001		2. NRC/REGIONAL OFFICE Region III	
3. DOCKET NUMBER(S) 150-00026	4. LICENSE NUMBER(S) NE 02-46-01	5. DATE(S) OF INSPECTION February 15, 2007	
6. INSPECTION PROCEDURES USED 87121	7. INSPECTION FOCUS AREAS 03.01 - 03.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03320	2. PRIORITY N/A	3. LICENSEE CONTACT Pennie Frye, RSO	4. TELEPHONE NUMBER 402-467-1818
-----------------------------	--------------------	---	-------------------------------------

Main Office Inspection
 Field Office
 Temporary Job Site

Next Inspection Date: N/A

Southern Star Pipeline, National & Weaver, Springfield, MO

PROGRAM SCOPE

The licensee was a State of Nebraska licensee operating at this site under reciprocity. Licensee staff used an AEA 660B radiography camera (Serial No. B4192) daily to check welds on a pipeline. Personnel present at this site performed no maintenance on the camera.

Performance Observations

The inspector observed operations at a temporary job site in Springfield, Missouri. The personnel and equipment were as described to the NRC. The radiographer and assistant described radiographic operations and emergency procedures for the camera, as well as security during transport and during operations, and the inspector noted no concerns. Shipping papers which contained all required information were accessible in the transport vehicle and the camera was properly secured in the vehicle. The radiographer and assistant were wearing all required dosimetry. The inspector performed independent radiation measurements of the transport package which indicated levels appropriate to its shipping classification, labeling and marking.