



RECEIVED
REGION I

NMSB2

Licensing Assistance Section ²⁰⁰⁷ FEB -1 PM 1: 05 February 22, 2007
US NRC Region I
475 Allendale Rd.
King of Prussia, PA 19406-1415

CLINICAL CARDIOLOGY
PHILIP L. LEBOVITZ, MD, FACC
ALAN G. STERN, MD, FACC
CHARLES F. PARABOSCHI, MD, FACC
WILLIAM E. COSTANZO, MD, FACC
RICHARD L. HYMAN, MD, FACC
WILLIAM S. HIRSCH, DO, FACC
STEVEN M. GOLDSMITH, MD, FACC
KEITH J. FISHBEIN, MD, FACC
STEVEN A. SAMUEL, MD, FACC
RIM AL-BEZEM, MD, FACC
PAULA S. SETH, MD
DONALD C. HAAS, MD

INTERVENTIONAL CARDIOLOGY
GEORGE P. HEYRICH, MD, FACC
DAVID W. DRUCKER, MD, FACC
SUNDER VENKATESULU, MD, FACC
SAMUEL W. MADEIRA, MD, FACC
ANDREAS WOLF, MD, FACC, FSCAI

ELECTROPHYSIOLOGY 
BRADFORD C. SODOWICK, MD, FACC
MICHAEL J. ROZENGARTEN, MD
SCOTT W. BURKE, MD
RAFAEL E. PENIA, MD
JOANN HORAN, PA-C

NURSE PRACTITIONERS
DENISE MAX, NP
KAREN GIQUINTO, NP
DEBORAH BOB, NP
ANDREW THOMAS, NP
STACEY NIEVES, NP
LINDA BARTLESON, NP

407 FLORAL VALE BLVD.
YARDLEY, PA 19067
PHONE 215-860-3344

2700 SOUTH EAGLE RD.
2ND FLOOR
NEWTOWN, PA 18940
PHONE 215-860-3344

1235 WHITEHORSE-MERCERVILLE RD.
BUILDING C, SUITE 317
MERCERVILLE, NJ 08619
PHONE 609-585-2040

3140 PRINCETON PIKE
2ND FLOOR
LAWRENCEVILLE, NJ 08648
PHONE 609-895-1919

WWW.MERCERBUCKSCARDIOLOGY.COM

Re : **Amendment Request for Mercer Bucks Cardiology,**
License #: 37-30825-01

03036288

Dear Licensing Specialist,
I am requesting an amendment to the above referenced license in order to:

1. **Add the following location of use:**
1 Union Street, Suite 101
Robbinsville, NJ 08691

This requested item is related to the acquisition of that site by Mercer Bucks Cardiology from Comprehensive Cardiology Consultants. They will be simultaneously submitting an amendment request to remove that location of use from their existing NRC Radioactive materials license #: **29-30950-01**. These requests should be coordinated so that control of the existing QC sources can be transferred to Mercer Bucks control, and so that patient care will not be interrupted. See attached information sheet.

A diagram of the existing facility is attached for your review.

All other aspects of the program will remain the same.

We have concurrently submitted a licensing request to the State of New Jersey, licensing assistance office in order to make these changes, as well.

If you have any questions or need any additional information please contact me at your convenience at (215) 860-3344.

Sincerely,

William Costanzo, M.D., Partner


Attachments: Facility Information Sheet Facility Diagram

140140

REC'D IN LAT FEB 28 2007

NM69/PGIN MATERIALS-002

**Mercer Bucks Cardiology
Existing Layout of the Nuclear Facility
At 1 Union Street Suite 101, Robbinsville, NJ 08691**



The nuclear cardiology lab will be on the first floor of a commercially constructed building.

Flooring is cement slab, and the hot lab, camera room and stress room (controlled areas) are along an outside wall, on the first floor.

This is to acknowledge the receipt of your letter/application dated

1/22/2007, and to inform you that the initial processing which includes an administrative review has been performed.

- AMEND. 37-30825-01 There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.
- Please provide to this office within 30 days of your receipt of this card
-

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned Mail Control Number 140140.
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.