

Perry Buckberg - RE: Inspection Exit Meeting –Plymouth – 01.30.07

From: Perry Buckberg
To: Mary Lampert
Date: 2/1/2007 1:11 PM
Subject: RE: Inspection Exit Meeting –Plymouth – 01.30.07

Mary,

Attached is the presentation Region I made on Tuesday.

The license renewal schedule was not updated in time to reflect the meeting - it was my error. The meeting notice was placed on NRC's public site January 17th and the press release was made on Jan. 23rd.

Thanks,
Perry

>>> "Mary Lampert" <mary.lampert@comcast.net> 1/31/2007 2:17 PM >>>
Perry:

RE: Inspection Exit Meeting -Plymouth - 01.30.07

Please send electronically [not in wpd- many can not open those documents] - slides presented last evening - as discussed the public was not properly notified and many interested parties were unable to attend.

Thanks you,

Mary Lampert
Pilgrim Watch

Mail Envelope Properties (45C22D34.4CB : 9 : 8248)

Subject: RE: Inspection Exit Meeting –Plymouth – 01.30.07
Creation Date 2/1/2007 1:11:00 PM
From: Perry Buckberg
Created By: PHB1@nrc.gov

Recipients	Action	Date & Time
comcast.net mary.lampert (Mary Lampert)	Transferred	2/1/2007 1:11:23 PM

Post Office	Delivered	Route
		comcast.net


Files	Size	Date & Time
MESSAGE	1624	2/1/2007 1:11:00 PM
TEXT.htm	1969	
Pilgrim LR Exit Slides with drywell_1.ppt PM	192512	1/29/2007 3:20:46

Options

Auto Delete: No
Expiration Date: None
Notify Recipients: Yes
Priority: Standard
ReplyRequested: No
Return Notification: None


Concealed Subject: No
Security: Standard

To Be Delivered: Immediate
Status Tracking: Delivered



Introductions

- Glenn Meyer, Team Leader
- NRC Participants
- Entergy Participants



Meeting Purpose

- Present Inspection Results to Entergy
- Provide Entergy Opportunity to Respond

Agenda


- Begin with General Process Discussion
- Conduct Exit Meeting
- End with Public Questions to NRC




License Renewal Rule

- Law & Regulation
- Process
- Safety Scope


License Renewal Process




Pilgrim Safety Review Track



Pilgrim Environmental Review






Safety Scope

- Safety Systems
- Some Non-safety Systems
- Systems Related to Special Regulations




Inspection

- Performed by Region I
- Six inspectors for two weeks in September & October 2006
- Follow up in December 2006




Inspection Activities

- Walk downs of plant systems & structures
- Review of Aging Management Programs
- Review of procedures and records




Inspection Results


- One open issue to be resolved during license renewal process – drywell
- Seven closed issues, including one with follow-up inspection
- If drywell issue resolved, reasonable assurance of management of aging



Drywell Issue

- Staff Guidance
- Pilgrim position
- Inspection determinations





Scoping Issue

- Non-safety systems directly connected to safety systems – unclear boundaries
- Additional Entergy evaluation effort
- Follow-up inspection



Closed Items

- Heat Exchanger Monitoring
- Diesel Fuel Oil Monitoring
- Lube Oil Analysis
- Concrete Monitoring
- Buried Piping Inspection
- Plant Stack Foundation




Entergy Response



Public Questions

Pilgrim License Renewal Inspection Exit Meeting



Nuclear Regulatory Commission

Plymouth, MA

January 30, 2007