



Metal Management, Inc.

Metal Management Aerospace, Inc.

NMSBZ

3/6/07

Mr. Stephen Courtemarche
U.S. NRC Region I
475 Allendale Road
King of Prussia, PA 19406-1415

030 35806

Termination Notice NRC license 06-30670-01.

Dear Mr. Courtemarche,

Metal Management Aerospace has permanently terminated the activities licensed under NRC license 06-30670-01. In accordance with the terms of this license, we possessed only sealed sources of Cd 109.

The sealed sources of Cd-109 used under this license were leak tested prior to transferring them to RAM Services (State of Wisconsin license #71-1234-01) for disposal. The leak tests on the sealed sources detected less than 0.005 microcuries of radioactive material prior to removal for disposal. Wipe tests on the instruments that used these sealed sources detected less than 0.005 microcuries of radioactive material left on the instruments.

During the life of this license, we did receive three sealed sources that 6 month leak tests showed to be leaking. Radiation Safety Associates, Hebron, CT removed the leaky sources decontaminated the instruments as documented in letters mailed to the NRC dated August 4, 2003, January 9, 2003 and January 14, 2003. No other sources other than the ones documented in these letters were found to leak during the life of this license.

Enclosed is a copy of a letter from RAM services, taking ownership of the sealed sources of Cd 109.

We request that you terminate our NRC license 06-30670-01.

Very Truly Yours,

Dan Mullen
Metal Management Aerospace

cc: Dr Edward Wilds, CT DEP

2007 MAR 8 PM 12: 21
RECEIVED
REGION 1

140 196

NRC/REGION 1 MATERIALS-002



510 County Highway V
Two Rivers, WI 54241
Voice +1-920-686-3889
Fax +1-920-686-3899

05 March 2007

Mr. Seb Cannata
radiac Research Corp.
261 Kent Avenue
Brooklyn, NY 11200

Reference: RAMPAK 162 (radiac B.O.L #77129-01).

Dear Mr. Cannata,

This letter confirms that on 01 March 2007 RAM Services, Inc. received several CD-109 sealed sources, detailed below, and took possession of this radioactive material under our State of Wisconsin Radioactive Materials License 71-1234-01. This information was taken from documentary materials provided by radiac and may be subject to correction. We cannot yet compute the current activity since we do not have a reference date for the nominal activity. Please inform me if any corrections are required since we will not open this package for some time.

Source_SN	Source_Manufacturer	Source Model	Isotope	Nom. Activity (mCi)
B1-581 / B1-582 / B1-583	ISOTOPES PRODUCTS LABORATORIES	3205-00	CD-109	20
J-107	JOHN HARRISON	0202	CD-109	20
A2-234	ISOTOPES PRODUCTS LABORATORIES	0102	CD-109	20
B1-584 / B1-585 / B1-586	ISOTOPES PRODUCTS LABORATORIES	3205-00	CD-109	20

These items were originally collected by radiac from Metal Management Aerospace and was identified as your package number 77129-01.

Please retain this record in your permanent files and do not hesitate to contact me at 920-686-3889 with any questions you may have. I can also be reached via email at jwiza@aol.com.

Sincerely,

Jerry P. Wiza,
Radiation Safety Officer

140186

Providing Leadership In **Recycling & Raw Material** Management



Metal Management, Inc.

Aerospace
500 Flatbush Ave.
Hartford, CT 06106
www.mtlm.com

Mr. Stephen Courtemarche
U.S. NRC Region I
475 Allendale Road
King of Prussia, PA 19406-1415



UNITED STATES POSTAGE
PITNEY BOWES
02 1P \$00.39⁰
0002368657 MAR 07 2007
MAILED FROM ZIP CODE 06106

19406+1431



This is to acknowledge the receipt of your letter/application dated

3/6/2007, and to inform you that the initial processing which includes an administrative review has been performed.

TEAM, 06-30570-01 There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned Mail Control Number 140196.
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.