

**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED: V.C. Consulting, LLC G 5067 W. Bristol Rd., Suite B Flint, MI 48507		2. NRC/REGIONAL OFFICE REGION III US NUCLEAR REGULATORY COMMISSION 801 WARRENVILLE ROAD LISLE IL 60532-4351	
REPORT NUMBER(S) 2006/001,2006/002			
3. DOCKET NUMBER(S) 030-37038	4. LICENSE NUMBER(S) 21-32596-01	5. DATE(S) OF INSPECTION 11/27/06-3/8/07	

**LICENSEE:**

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.


\_\_\_\_\_ non-cited violation(s) were discussed involving the following requirement(s):

- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

(Violations and Corrective Actions)

**Statement of Corrective Actions**

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE			
NRC INSPECTOR	Sarah Bakhsh		03/08/2007

### SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION


1. LICENSEE/LOCATION INSPECTED: V.C. Consulting 2235 S. Linden Road Flint, MI 48532  REPORT NUMBER(S) 2006/001,2006/002		2. NRC/REGIONAL OFFICE REGION III US NUCLEAR REGULATORY COMMISSION 801 WARRENVILLE ROAD LISLE IL 60532-4351	
3. DOCKET NUMBER(S) 030-37038	4. LICENSE NUMBER(S) 21-32596-01	5. DATE(S) OF INSPECTION 11/27/06-3/8/07	

**LICENSEE:**  
The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

- 1. Based on the inspection findings, no violations were identified.
- 2. Previous violation(s) closed.
- 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.  
  
\_\_\_\_\_ non-cited violation(s) were discussed involving the following requirement(s):
  
  
  
  
  
  
  
  
  
  
- 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.  
  
(Violations and Corrective Actions)

#### Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE			
NRC INSPECTOR	Sarah Bakhsh		03/08/2007

**Docket File Information**  
**SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION**

1. LICENSEE/LOCATION INSPECTED: V.C. Consulting, LLC REPORT NUMBER(S) 2006/001,2006/002		2. NRC/REGIONAL OFFICE REGION III	
3. DOCKET NUMBER(S) 030-37038	4. LICENSE NUMBER(S) 21-32596-01	5. DATE(S) OF INSPECTION 11/27/06-3/8/07	
6. INSPECTION PROCEDURES USED IP 87130		7. INSPECTION FOCUS AREAS 03.01-03.07	

**SUPPLEMENTAL INSPECTION INFORMATION**

1. PROGRAM CODE(S) 02201	2. PRIORITY 5	3. LICENSEE CONTACT Dr. Subhash Khullar, RSO	4. TELEPHONE NUMBER 810-230-9553
-----------------------------	------------------	---	-------------------------------------

- Main Office Inspection      Next Inspection Date: 11/2011
- Field Office Inspection    2235 S. Linden Road
- Temporary Job Site Inspection \_\_\_\_\_

**PROGRAM SCOPE**

This was an initial inspection of the licensee, with an onsite inspection on 11/27/06 and continued in-office review through 3/8/07. The licensee's facilities were small medical clinics located in Flint, Michigan, and one in Rochester Hills, Michigan. The licensee was authorized to conduct licensed activities under 10 CFR 35.100 and 35.200. At the Bristol Road location, the licensee employed two full-time nuclear medicine technologists (NMT) who performed approximately 40-50 diagnostic studies weekly using technetium-99m in unit doses. The South Linden location employed three full-time (a few of which rotate from the other locations) technologists who performed approximately 25 diagnostic procedures weekly using technetium-99m in unit doses. The unit doses were delivered from a local pharmacy. All waste was either held for decay-in-storage or returned to the pharmacy.

Both the South Linden and Bristol Road locations of use were inspected during the 11/28/2006 inspection. The inspector also completed TI 2800/039 for both locations of use.

**PERFORMANCE OBSERVATIONS**

During the inspection, the inspector reviewed select records (dose records for NMT present at the South Linden facility during the inspection were not available) and observed: (1) administration of the radioactive material by the technologist; (2) adequate security of the licensed material; (3) adequate posting of areas; (4) package receipt and return surveys; (5) responses to emergency scenarios; (6) survey meter use and calibration; (7) daily and weekly contamination surveys; and (8) dose calibrator constancy checks.

No violations of NRC requirements were identified.