

FAX COVER SHEET

Radiological Physics Service, Inc.
 3839 Napier Road
 Plymouth, MI 48170
 (734) 455-4730
 Fax (734) 453-8851

MR TARIK L. LICENSING

Send to: MR C	From: Ray Carlson
Fax Number: 630-829-9782	Date: 3/31/07

- ☐ Urgent
☐ Reply ASAP
☐ Please comment
☐ Please review
☐ For your information

Total pages, including cover: **5**

Comments:

--

Radiological Physics Service, Inc.

Ray A. Carlson, M.S.

President

Medical Nuclear & Diagnostic Physicist
 Certified American Board of Radiology
 American Board of Medical Physics

(734) 455-4730
 3839 Napier Road
 Plymouth, MI 48170

E-Mail: rcarlson@voyager.net
 Cell (734) 395-7361
 FAX (734) 453-8851

CWO-4 U.S.M.C. (Retired)

Radiological Physics Service, Inc.

Dan L. Marx, M.S., M.B.A.

Medical Health Physicist

(734) 455-4730
 (734) 453-8851 (Fax)
 3839 Napier Road
 Plymouth, MI 48170

Cell: (810) 730-6004
 Home: (810) 631-8914

Major U.S. Army (Retired)

Radiological Physics Service, Inc.

• 3839 Napier Road – Plymouth, Michigan 48170 • (734) 455-4730 • fax: (734) 453-8851

March 19, 2007

U. S. NUCLEAR REGULATORY COMMISSION

Region III

Materials Licensing Branch

2443 Warrenville Road, Ste 210

Lisle, IL 60532-4352

RE: Survey of Facility for License #21-32298-01, Regional Cardiology, 2486 Nerredia, Ste E, Flint, MI 48532

The decommission survey of the Regional Cardiology, 2486 Nerredia, Ste E, Flint, MI 48532-4807 location under license #21-32298-01 was performed on March 19, 2007.

The results of the survey are: All surveys and wipes tests prove to be below background measurements. The following methodology was performed:

1. A comprehensive survey of the entire Nuclear Hot Lab, and all stress lab room and imaging Gamma Camera areas, were performed using a GM end window survey meters. Surveys were performed at the most sensitive setting. All survey results proved to be below background measurements. (Survey locations are indicated on attached map). The following meter was used:
 - a. Ludlum GM Model 14C – Recently Calibrated (8/3/06)
2. Wipe tests were performed on twenty-two (22) locations (indicated on attached map). Wipe tests were counted in a Capintec CRC-15W well, for 1 minute.

Window 0-600keV

Hot Lab


1. Countertop at Dose Drawing Area
2. Background – outside of lab in hallway
3. Dose Drawing area floor
4. Hot Lab Waste Storage undercabinet area
5. Entrance to Hot Lab at door
6. Countertop at door end
7. Closet in Hot Lab
8. Stress Lab (downstairs) Entrance
9. Patient table (1) in Stress Lab
10. Patient table (2) in Stress Lab
11. Patient floor area (1) in Stress Lab
12. Patient floor area (2) in Stress Lab
13. Imaging room Gamma table (1) Downstairs

14. Imaging room floor (1) downstairs
15. Imaging room Gamma table (2) downstairs
16. Imaging room floor (2) downstairs
17. Stress treadmill area upstairs
18. Stress area floor upstairs
19. Imaging room upstairs camera area
20. Imaging room upstairs on floor near camera area
21. Control panel of upstairs imaging room equipment
22. Control panel of downstairs imaging room equipment


All wipes were below 2000 dpm. All wipe areas were also surveyed with the GM survey meter and all areas recorded less than 0.03 mR/hr.

All Sealed sources were leak tested. All leak testing was background prior to and after transport.


If there are any further questions please contact survey nuclear medical physicist Laura T. Smith, MS at (586) 215-5947 or pager 313 609-2038.



License #21-32298-01, Regional Cardiology, 2486 Nerredia, Ste E, Flint, MI 48532
3/19/2007



Hallway



**License #21-32298-01, Regional Cardiology, 2486 Nemedra, Ste E, Flint, MI 48532
3/19/2007**

