NRC FORM 591M PAR	T 1		U.S. NUCLEAR REGULATORY COMMISSION		
(10-2003) 10 CFR 2.201	SAFETY INS	PECTION REPORT	AND COMPLIANO	CE INSPECTION	
LICENSEE/LOCATION INSPECTED: Massey Energy Company Alex Energy Inc., Superior Surface Mine P.O. Box 1078 Holden, WV 25625 REPORT 2007-001			2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415		
3. DOCKET NUMBER(4. LICENSE NUMBER(S)	5. DATE(S) OF INSI	PECTION
030-36608	,	47-30927-01	,	March 21-2	
LICENSEE:					······································
Nuclear Regulatory Corr of procedures and repre 1. Based on th 2. Previous vid 3. The violatio identified, non-	nmission (NRC) rules and sentative records, intervi ne inspection findings, no plation(s) closed. n(s), specifically describe	d regulations and the con- iews with personnel, and on the con- portion of the control of the co	ditions of your license. bbservations by the ins d. as non-cited violations	to radiation safety and to cor The inspection consisted of pector. The inspection finding s, are not being cited becaus p criteria in the NRC Enforce	selective examinations sings are as follows:
Non-C	ited Violation(s) was/wer	re discussed involving the	following requirement(s) and Corrective Action(s):	
	is form is a NOTICE OF	VIOLATION, which may	be subject to posting in	were in violation of NRC rec accordance with 10 CFR 19	
corrective actions is mad	n 30 days, the actions de de in accordance with the ce will be achieved). I un	e requirements of 10 CFF	ector will be taken to c 2.201 (corrective step	Item 4, above. correct the violations identifies a already taken, corrective so will be required, unless specific signature	teps which will be taken,
LICENSEE'S REPRESENTATIVE					
NRC INSPECTOR	Michael R	eichard	111:1.1	1 Roile	(13/22/07