

**DPO-2006-002: Oconee ECCS Sump Screens**

Subject: This DPO raises concerns about new ECCS sump screens at the Oconee facility. The submitter contends that the new sump screens can be impacted by jet impingement from an RCS cold leg break (LOCA) and that the licensee should be required to perform an analysis (per GDC-4) prior to installation.

Assigned to: Jim Dyer, NRR OD

**DPO Milestones and Timeliness Goals** ~

<b>DPO Milestone</b>	<b>Timeliness Goals</b>	<b>Actual Date</b>
Individual submits DPO (NRC Form 680)	None	05/12/2006
DPOPM screens and accepts DPO	8 CDs	05/12/2006
DPOPM assigns DPO to OD or RA	5 CDs	05/22/2006
OD or RA establishes DPO Panel <sup>1</sup>	14 CDs	06/02/2006
DPO Panel meets with submitter <sup>2</sup>	8 CDs	07/20/2006
DPO Panel collects, reviews, and evaluates information	30 – 90 CDs	07/20/2006 08/15/2006
DPO Panel writes report	30 CDs	In Process
OD or RA comments on DPO Panel report submitter comments on DPO Panel report	10 CDs	
DPO Panel evaluates comments and either revises report or declares original report final	7 CDs	
OD or RA issues DPO Decision	21 CDs	
<b>TOTAL CDs (from acceptance of DPO)</b>	<b>130 – 190 CDs</b> 08/19/2006- 11/18/2006 ~	

---

<sup>1</sup>Given the scope of the concerns, the NRR, OD established one DPO Panel to address DPO-2006-002 and DPO-2006-003.

<sup>2</sup>Unanticipated scheduling issues delayed the meeting with the submitter.