

NMSBL

May 7, 2007

U.S. Nuclear Regulatory Commission
Region I
Nuclear Material Section B
475 Allentown Road
King of Prussia, PA 19406


RE: Amendment request
Sacred Heart Hospital
Docket No. 030-02961
License No. 37-00554-03

Dear Sir or Madam:

We no longer use byproduct material permitted by 35.11 for in vitro studies and therefore request this item be removed from the above referenced license. These studies were performed several years ago in our Hematology Lab. In accordance with the guidelines established by the NRC, dated December, 1975, "Guidelines for Decontamination of Facilities and Equipment Prior to Release for Unrestricted Use", we herein submit the final survey of the area. Malek Daneshvar of Krueger-Gilbert Health Physics, Inc. performed this survey on February 13, 2007. Please refer to enclosures.

If you have any questions regarding this request, please contact the undersigned or Malek Daneshvar of Krueger-Gilbert Health Physics, Inc. at (410) 665-5447.

Sincerely,



Ralph Natale
Radiation Safety Officer

Enclosures

140533

NMSS/RGN1 MATERIALS-002

REC'D IN LAT MAY 21 2007

SURVEY RESULTS
Waste Storage Room

Survey Date: February 13, 2007
Instrument: Ludlum 3, # 94423
Calibration Date: November 22, 2007
Background: 0.02 to 0.03 mR/hr

Sample	Survey Meter
<u>Location</u>	<u>Reading</u>
Floor	0.02 – 0.03 mR/hr
Walls	0.02 – 0.03 mR/hr
Door	0.02 – 0.03 mR/hr

WIPE TEST RESULTS
Hematology Lab

Survey Date: February 13, 2007
Instrument: Ludlum scaler model 2200 #74451
Detector Efficiency: Cs-137 (662 KeV) = 12.2%
Ba-133 (356 KeV) = 22.4%
Co-57 (122 KeV) = 77.6%
Background count: 2345 counts/10 minutes or 234 cpm

Sample	Results
<u>Location</u>	<u>(Net)</u>
1 through 14	< 100 cpm - floor
19 through 30	< 100 cpm – walls
31 through 33	< 100 cpm– door
34	< 100 cpm – light switch

This is to acknowledge the receipt of your letter/application dated

5/7/2007, and to inform you that the initial processing which includes an administrative review has been performed.

AMEND. 37-00554-03
There were no administrative omissions. Your application was assigned to a technical reviewer. Please note that the technical review may identify additional omissions or require additional information.

Please provide to this office within 30 days of your receipt of this card

A copy of your action has been forwarded to our License Fee & Accounts Receivable Branch, who will contact you separately if there is a fee issue involved.

Your action has been assigned Mail Control Number 140533.
When calling to inquire about this action, please refer to this control number.
You may call us on (610) 337-5398, or 337-5260.