

Docket File Information
**SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION**

1. LICENSEE Cal testing Services, Inc REPORT 2007-001	2. NRC/REGIONAL OFFICE Region III
--	---

3. DOCKET NUMBER(S) 03020915	4. LICENSE NUMBER(S) 13-23323-01	5. DATE(S) OF INSPECTION May 14, 2007
---------------------------------	-------------------------------------	--

6. INSPECTION PROCEDURES USED 87124	7. INSPECTION FOCUS AREAS 03.01 - 03.07
--	--

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 03121	2. PRIORITY 5	3. LICENSEE CONTACT Thomas Keilman	4. TELEPHONE NUMBER 219.923.9800
-----------------------------	------------------	---------------------------------------	-------------------------------------

<input checked="" type="checkbox"/> Main Office Inspection	Next Inspection Date: <u>May 2012</u>
<input type="checkbox"/> Field	
<input type="checkbox"/> Temporary Job Site	

PROGRAM SCOPE

^{is}
The licensee is a radiography company that employs 25 individuals. The licensee possesses one Troxler moisture density gauge (Serial No. 8246), for use daily/weekly during the construction season (May-November) for soils engineering projects. The licensee does not perform any service or maintenance activities on its gauges; these services are performed by the manufacturer. Currently, the licensee employs two authorized gauge users who have completed manufacturers training.

Performance Observations

At the time of this inspection, the gauges were not in use. The operator possessed required shipping papers which contained all appropriate information and were accessible in the transport vehicle. Gauge/case were locked and chained in the radiography area of the vehicle during transport. The operator demonstrated an adequate level of understanding of emergency and handling procedures during job-site interviews. Security during transport and at the job-site was described and observed respectively with no problems noted. The inspector performed independent and confirmatory radiation measurements which indicated similar results as noted in the licensee's survey records.

The last inspection was conducted by Tony Go on May 28, 2002, with no violations found.