

UNION CARBIDE CHEMICALS COMPANY

DIVISION OF  
UNION CARBIDE CORPORATION



SOUTH CHARLESTON, W. VA.

September 18, 1957

590.

*[Handwritten signature]*

*[Handwritten signature]*

Mr. G. W. Morgan  
Chief  
Isotopes Extension  
Division of Civilian Application  
United States Atomic Energy Commission  
Oak Ridge  
Tennessee

Reference: IEB:REB (LIC 47-260-2)

Dear Mr. Morgan:

The subject letter lists two deficiencies in our operations with regard to provisions of "Licensing of Byproduct Material" contained in Title 10, Code of Federal Regulations, Part 30. These deficiencies are restated below together with a description of action taken:

(a) 200 millicuries of Cobalt 60 not licensed.

Action: An order has been placed to dispose of this material by burial at Oak Ridge. This order should be completed within a 30 to 60 day period.

(b) Posting of areas with radiation levels exceeding 5 mr/hr.

Action: Old warning signs have been removed and new ones mounted which conform to the exact wording required in the latest revision of the Code.

It is hoped that this action will satisfy the requirements of the regulations, and that the next inspection will verify our complete conformity to the provisions contained in the Code.

Very truly yours,

*L. J. Rogers*

Chairman  
Radioactive Materials Committee  
Special Instrumentation Dept.  
INSTRUMENT DIVISION

ORO

LJRogers/jf

A-5