

July 30, 1963

**Kber R. Price, Assistant Director  
Division of Licensing and Regulation**

**Leo Dublaski, Assistant Director for Materials  
Division of Compliance**


**COMPLIANCE INSPECTION REPORT FOR UNION CARBIDE CHEMICALS  
COMPANY, SOUTH CHARLESTON, WEST VIRGINIA; INSPECTION  
CONDUCTED ON APRIL 23 - 25, 1963 - LICENSE NO. 47-260-6**

CO:HEJ

In response to R. G. Page's memorandum of July 19, 1963, subject as above, we have contacted Region II, Division of Compliance. They have informed us that the reference to three-year leak tests in paragraph 37 of the report is an error and should be disregarded; the licensee was in compliance with Condition No. 15(c) of the license.

License Nos. -2 and -7 allow for three-year leak tests of certain Cs-137 sealed sources. AEC-591 forms were issued as a result of the inspection of these two licenses.

cc: G. A. Blanc, CO:II



A-20