



**TXU Power**  
Comanche Peak Steam  
Electric Station  
P. O. Box 1002 (E01)  
Glen Rose, TX 76043  
Tel: 254 897 5209  
Fax: 254 897 6652  
mike.blevins@txu.com

**Mike Blevins**  
Senior Vice President &  
Chief Nuclear Officer

CPSES-200700951  
Log # TXX-07091

June 19, 2007

U. S. Nuclear Regulatory Commission  
ATTN: Document Control Desk  
Washington, DC 20555

**SUBJECT: COMANCHE PEAK STEAM ELECTRIC STATION (CPSES)  
DOCKET NO. 50-445  
UNIT 1 PRESSURIZER WELD OVERLAY 60 DAY REPORT AND  
UPDATE FOR UNIT 1 REACTOR PRESSURE VESSEL HEAD  
REPLACEMENT REGARDING REVISED ORDER EA-03-009**

- REF:**
1. TXU Power letter, logged TXX-07013, from Mike Blevins to the NRC dated January 30, 2007
  2. TXU Power letter, logged TXX-07079, from Mike Blevins to the NRC dated April 5, 2007
  3. NRC Letter dated February 20, 2004, Issuance of First Revised NRC Order (EA-03-009) Establishing Interim Inspection Requirements for Reactor Pressure Vessel Heads at Pressurized Water Reactors

Dear Sir or Madam:

By means of Reference 1, TXU Generation Company LP (TXU Power) committed to submit a report with the results of future inspections or mitigation of Pressurizer Alloy 82/182 butt weld locations within 60 days of startup from the outage during which they were performed.

Pressurizer Alloy 82/182 butt weld structural weld overlay was completed for Unit 1 during refueling outage 1RF12 which ended April 20, 2007. Reference 2 submitted the required information on April 5, 2007. No further action is required for Unit 1 Pressurizer Alloy 82/182 butt welds.

A member of the **STARS** (Strategic Teaming and Resource Sharing) Alliance

Callaway • Comanche Peak • Diablo Canyon • Palo Verde • South Texas Project • Wolf Creek

A110

MRR

TXX-07091  
Page 2 of 2

During Unit 1 refueling outage 1RF12 the reactor pressure vessel head was replaced. Per Reference 3, no inspections were required during this outage. The type and frequency of future inspections will be performed as required by Section IV.C.(4) of Reference 3 for a replaced reactor pressure vessel head.

This communication contains no new or revised licensing basis commitments for CPSES.


If you have any questions or need additional information regarding this matter, please feel free to contact Jack Hicks at (254) 897-6725.

Sincerely,

TXU Generation Company LP

By: TXU Generation Management Company LLC,  
Its General Partner

Mike Blevins

By:   
Fred W. Madden  
Director, Oversight and Regulatory Affairs

JCH

c - B. S. Mallett, Region IV  
M. C. Thadani, NRR  
Resident Inspectors, CPSES