



UNITED STATES
ATOMIC ENERGY COMMISSION
DIRECTORATE OF REGULATORY OPERATIONS
REGION II - SUITE 818
230 PEACHTREE STREET, NORTHWEST
ATLANTA, GEORGIA 30303

TELEPHONE: (404) 526-4503

JAN 5 1973

J. B. Henderson, Chief, Reactor Construction Branch
Directorate of Regulatory Operations, Headquarters

TENNESSEE VALLEY AUTHORITY (WATTS BAR 1, 2), DOCKET NOS. 50-390, 391
VENDOR INSPECTION - ROTTERDAM DOCKYARD COMPANY (RDM), REPORT NO.
999-39/72-4

Attached vendor inspection report No. 999-39/72-4 covering a
routine inspection by Brown on November 9-10, 1972, is for informa-
tion. There were no violations identified.

A handwritten signature in black ink, appearing to read "F. J. Long", is written over a horizontal line.

F. J. Long, Chief
Facilities Construction Branch

RO:II:FJL

Enclosure:
RO Rpt. No. 999-39/72-4
(Brown)

cc w/encl:
RO:HQ (5)
DR Central Files
Regulatory Standards (3)
Directorate of Licensing (13)
R. L. Brown, RO:I

cc encl. only:
*PDR
*Local PDR
*NSIC
*DTIE, OR

*To be dispatched at a later date.