


JUL-09-2007 13:30

USNRC R1 LAS

610 337 5393

P.02

NRC FORM 591M PART 1 <small>(10-2003) 10 CFR 2.201</small>		U.S. NUCLEAR REGULATORY COMMISSION	
SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION			
1. LICENSEE/LOCATION INSPECTED: Tri-State Medical Group, Inc. 1000 Stonewood East, Suite 110 Wexford, PA 15090		2. NRC/REGIONAL OFFICE U.S. Nuclear Regulatory Commission Region I, 475 Allendale Road King of Prussia, Pennsylvania 19406-1415	
REPORT Nos 200701			
3. DOCKET NUMBER(S) 030-32553	4. LICENSE NUMBER(S) 37-28705-01	5. DATE(S) OF INSPECTION May 15, 2007	
LICENSEE: The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:			
<input type="checkbox"/> 1. Based on the inspection findings, no violations were identified.			
<input type="checkbox"/> 2. Previous violation(s) closed.			
<input type="checkbox"/> 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.			
<input type="checkbox"/> Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):			
<input checked="" type="checkbox"/> 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.			
<p>10CFR35.61(a) requires that a licensee shall calibrate the survey instruments used to show compliance with 10 CFR Part 35 and 10 CFR Part 20 before first use, annually, and following a repair that affects the calibration. Contrary to this requirement, the calibration of the licensee's survey instrument had expired on February 20, 2007.</p>			
Licensee's Statement of Corrective Actions for Item 4, above.			
I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.			
Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Leslie HASTINGS		7-9-2007
NRC INSPECTOR	Todd J. Jackson, CHP		July 6, 2007

NRC FORM 591M PART 1 (Rev. by RI 07/06)

G:\Docs\Current\Nsp Record\R37-28075-01.2007001.591Part1.wpd

SUNSI Review Completed By: / RA /

Public

Non-Sensitive