

RAI 6.3-40, Supplement No. 1 (MFN 06-488, 12/22/06)

Staff is uncertain on why the minimum reactor pressure vessel (RPV) water level values stated in the response to RAI 6.3-40 do not correspond with the values provided in Table 6.3-5, "Summary of ECCS-LOCA Performance Analyses" of the DCD. Please explain.

Also, please revise the DCD to include the response to RAI 6.3-40.