

Sdp \ Exercise2 \
Exercise 2 issue
description.dcc

Exercise 2

Issue Description

On-line maintenance led to placing improper fuses in the control circuits of both PORVs. The problem was corrected two days after the improper fuses were installed. Subsequent investigation revealed that the PORVs would not have opened during the time the improper fuses were installed. Perform a significance determination of this issue.

- Using IMC-0612, determine if the SDP should be used to evaluate this issue.
- Using IMC-0609 and the Callaway pre-solved table, determine the color of the finding - if applicable.

C-15