

Exelon Generation Company, LLC www.exeloncorp.com
Byron Station
4450 North German Church Road
Byron, IL 61010-9794

July 31, 2007

LTR: BYRON 2007-0055
FILE: 1.10.0101

United States Nuclear Regulatory Commission
ATTN: Document Control Desk
Washington, DC 20555-0001

Byron Station, Unit 2
Facility Operating License No. NPF-66
NRC Docket No. STN 50-455

SUBJECT: Byron Station Unit 2 90-Day Inservice Inspection Report for Interval 3, Period 1, Outage 1 (B2R13)

The subject 90-day Inservice Inspection Report for the Byron Station Unit 2, Refueling Outage Thirteen (i.e., B2R13) is being submitted pursuant to the requirements of Article IWA-6000, "Records and Reports" of Section XI, "Rules for Inservice Inspection of Nuclear Power Plant Components," of the American Society of Mechanical Engineers Boiler and Pressure Vessel Code 2001 Edition through the 2003 Addenda. The report covers the inservice inspections conducted prior to and during the Unit 2 Spring 2007 refueling outage.

If there are any questions regarding this matter, please contact W. Grundmann, Regulatory Assurance Manager, at (815) 406-2800.

Respectfully,



David M. Hoots
Site Vice President
Byron Nuclear Generating Station

DMH/RGM/TLH/rah

Attachment: B2R13 Inservice Inspection Summary Report – Spring 2007 Outage