

Docket File Information
SAFETY INSPECTION REPORT
AND COMPLIANCE INSPECTION

1. LICENSEE Mid Michigan Radiology REPORT NUMBER(S) 2007-001		2. NRC/REGIONAL OFFICE Region III 2443 Warrenville Road Lisle, IL 60532	
3. DOCKET NUMBER(S) 030-32468	4. LICENSE NUMBER(S) 21-26346-01	5. DATE(S) OF INSPECTION 7/18/07	
6. INSPECTION PROCEDURES USED 87130	7. INSPECTION FOCUS AREAS 03.01-03.07		

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S) 2200	2. PRIORITY 3	3. LICENSEE CONTACT David Petrella, M.D.	4. TELEPHONE NUMBER 989-773-2081
-----------------------------------	-------------------------	--	--

Main Office Inspection Next Inspection Date: 7/2010
 Field Office _____
 Temporary Job Site _____

PROGRAM SCOPE

Licensee is a small cardiology clinic located in Mt. Pleasant, Michigan. This licensee uses only unit doses of technetium-99m for cardiac studies supplied by GE Health. The licensee has one technician for patient studies. The licensee sees approximately 4 patients per day at the clinic.

Performance Observations

The inspector toured the facility and conducted interviews of the staff. Each appeared knowledgeable in radiation safety and isotope handling techniques. Package receipt procedures were demonstrated for the inspector as well as rad waste handling practices. Independent surveys by the inspector did not detect any abnormal reading and were within the expected range.

The inspector observed the nuclear medicine staff perform injections of radiopharmaceuticals. Techniques employed by the staff demonstrated good handling practices as well as adequate knowledge of radiation safety. During the course of the inspection, no abnormalities were noted.

RP