

APPENDIX A

NOTICE OF VIOLATION

Tennessee Valley Authority

License No. CPPR-92

Based on the results of the NRC inspection conducted on August 9-11, 1978, it appears that certain of your activities were not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in our correspondence to you dated December 31, 1974.

Criterion V of Appendix B to 10 CFR 50, as implemented by the FSAR, paragraph 17.1A.5, requires, in part, that, "Activities affecting quality shall be prescribed by documented instructions, procedures, . . . and shall be accomplished in accordance with these instructions, procedures," Paragraph 13.4 of PDM Welding Specification WS40 prohibits the removal of temporary attachments by hammer blows only, i.e. without first mechanically cutting a failure line in the weld.

Contrary to the above requirement, on August 10, 1978, numerous areas were observed on the refueling water storage tank roof where temporary attachments had been removed by hammer blows only.

This is an infraction.

7810240207