

APPENDIX A

NOTICE OF VIOLATION

Tennessee Valley Authority
Watts Bar 1 and 2

License Nos. CPPR-91
CPPR-92

Based on the NRC inspection March 5-30, 1979, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required by Criterion XVII of Appendix B to 10 CFR 50, as implemented by the Watts Bar FSAR, Part 17.1A.17, TVA Construction inspection records shall identify the inspector, type of observation and results.

Contrary to the above, Watts Bar Quality Control Procedure WBNP-QCP-2.4, Erection and Inspection of Structural and Miscellaneous Steel, states that the Civil Engineer shall initial the weld inspection form to verify that the welding inspector has inspected the weld. There is no documentation of the type of inspection or inspection for pipe whip restraints.

This is a deficiency.

7907180623