

APPENDIX A

NOTICE OF VIOLATION

Tennessee Valley Authority  
Watts Bar, Units 1 and 2

License No. CPPR-91  
CPPR-92

Based on the NRC inspection May 29 through June 1, 1979, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required by Criterion V of Appendix B to 10 CFR 50 and as implemented by FSAR paragraph 17.1A.5, "Activities affecting quality shall be prescribed by documented instructions, procedures...and shall be accomplished in accordance with these instructions, procedures...". Process Specification 4.M.2.1(c) requires penetrant inspection of alignment bead welds and documentation of the size of the groove or bead for these welds.

Contrary to the above, on May 30, 1979, the penetrant inspections and documentation of the size of the groove or bead had not been performed for alignment bead welds identified as 1-072A-D063-08A and 2-087A-D017-01A.

This is an infraction.

7909200248