

APPENDIX A  
NOTICE OF VIOLATION

Tennessee Valley Authority  
Watts Bar, Units 1 and 2

License Nos. CPPR-91  
CPPR-92

Based on the NRC inspection April 30 through May 25, 1979, certain of your activities were apparently not conducted in full compliance with NRC requirements as indicated below. These items have been categorized as described in correspondence to you dated December 31, 1974.

As required by Criterion XV of Appendix B to 10 CFR 50, as implemented by the Watts Bar FSAR, Part 17.1A.15, TVA shall take the appropriate measures to identify and document nonconformances.

Contrary to the above, a nonconformance report was not issued when conduit, running from manholes to the diesel generator building was found obstructed with concrete.

This is a deficiency.

7909210644